



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1753

SECTION I : IDENTIFICATION

1. Name

Present : Banio ki haveli
 Past :
 Other Name (if any): :

2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

Address

Chirana ,Ward No.-21

: **Village (village code)** Chirana
Post : Chirana **District:** Jhunjhunu
State : Rajasthan **PIN:** 333303

Approach

: The Haveli is situated at Chirana. It is 62km from Jhunjhunu. It is well connected by regular private & govt. bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is an old and dilapidated haveli. It has a series of cusped arches at the exterior. The projected chhajjas are supported by stone brackets. The exterior is cluttered with waste products and garbage. The haveli is abandoned. Some vegetational growth can also be seen near the haveli.

4. Property Use

ABANDONED / IN USE : ABANDONED

Present :
Past : Residence

5. Age (Source)

PERIOD : 18th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | | |
|-------------------------------------|---------------------|---------------|
| <input checked="" type="checkbox"/> | Architectural | Dressed stone |
| <input type="checkbox"/> | Archaeological | |
| <input type="checkbox"/> | Historical | |
| <input type="checkbox"/> | Religious | |
| <input type="checkbox"/> | Any other (specify) | |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- | | | |
|------------------------------|--|--|
| Context | | * Drawings (Attach extra sheet if necessary) |
| Urban / Rural Setting | | Urban |
| Surroundings | | Stand in Isolation |
| | | Integral part of a Landscape / Street / Complex |

- | | | |
|-------------------------------|----|-----------------------|
| Quantification | | |
| Area Dimension (L x B x H) : | | (m / cm/ feet / inch) |
| Number of Blocks : | 01 | |
| Number of Storys : | 01 | |

- | | | |
|-----------------------------|--|--|
| Spatial Organization | | |
| Orientation : | The Haveli is oriented East-west and faces the east. | |
| Plan : | | |
| Allocation of Spaces : | | |

ARCHITECTURAL STYLE

- | | | |
|------------------------------|---|--|
| Ornamentation | | |
| Exteriors : | It has a dilapidated boundary wall. Projected chhajjas are supported by stone brackets. | |
| Interiors : | | |
| Movable Collections : | | |
| Any Other (specify) : | | |

10. Construction Technology

- | | | |
|---------------------------------|---|-----------------|
| Structural System | : | Indo-Persian |
| Building Techniques | : | Arcuate |
| Material of Construction | : | Brick and stone |

11. Condition Assessment

In General		Good / Fair
		Good

- | | |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Dilapidated.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input type="checkbox"/> | Natural |
| <input checked="" type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS