

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-1805

| SECTION I : IDENTIFICATION 1. Name | | | | |
|-----------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| Present Past Other Name (if any): 2. Location | : Panch Pandav Dham : | | | |
| LONGITUDE 75° 4' E | LATITUDE 28 ⁰ 13' N | | | |
| Address | | | | |
| Approach | And 5 KM from Bus s | Lohargal District: Jhunjhunu PIN: 333303 Iohargal near Gopinath temple. tand Golyana. It is 68 Km from ected by regular bus services | | |
| 3. Property Type | | | | |
| Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building | Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum | Other Structures Wall Gateway Pillar Others (specify) | | |
| Engineering structure Bridge Tunnel Other engineering structure | Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave | Note: It is a modern temple having stone images of five Pandavas attired in a traditional clothing adorn the main shrine. The walls are adorned with glared marble tiles. An image of Krishna is in the centre and an image of Draupadi is at the corner. The temple is painted red. | | |

| 4. Property Use | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|------------------------------------|
| | | ABANDONED / IN USE : IN USE |
| Present Past | | Religious Religious |
| 5. Age (Source) | | |
| PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection | : : : : : : : : : : : : : : : : : : : : | Pauranik |
| o. Ownerding / Level of Froteoti | <u> </u> | SINGLE /MULTIPLE : |
| Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone | : : : : : : : : : : : : : : : : : : : : | SINGLE/MOETH EE: |
| 7. Association | | |
| WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) | : : : : : : : : : : : : : : : : : : : : | Being used for religious purposes. |
| 8. Statement of Significance | | |
| Architectural Archaeological Historical Religious Any other (specify) | Bric | k and dressed stone. |

SECTION II: DESCRIPTION

| 9. | Physical Description and De | cor | ative Features | |
|-----------|---------------------------------------------------------------------|-------|----------------------------------------------------------------------------------------------------------------------------------|--|
| • | Context Urban / Rural Setting Surroundings | | * Drawings (Attach extra sheet if necessary) Hill side | |
| | | | Stand in Isolation Hilly setting Integral part of a Landscape / Street / Complex | |
| • | Quantification Area Dimension (L x B x H) | : | (m / cm/ feet / inch) | |
| | Number of Blocks Number of Storys | : | 01 01 | |
| • | Spatial Organization Orientation Plan Allocation of Spaces | : : : | The temple is oriented North-south and faces the North. | |
| <u>AF</u> | CCHITECTURAL STYLE Ornamentation Exteriors | : | The main shrine has decorative stone images of for Pandavas with Krishna and Draupadi. Glared mark tiles were used on the walls. | |
| An | Interiors Movable Collections y Other (specify) | : : | thes were used on the walls. | |
| 10 | . Construction Technology | | | |
| 44 | Structural System Building Techniques Material of Construction | : : | Modern Brick and stone masonary Brick and stone. | |
| 11 | . Condition Assessment In General G | boo | / Fair Good | |
| | Sign of Deterioration Serious Deterioration Danger of Disappearance | . 34 | | |
| In | Brief (Attach extra sheet if n | ece | ssary): | |
| Th | e temple is well maintained. | | | |

| 12. Threats to the Property | |
|-----------------------------|------------------------------------------------|
| | ✓ Natural Negligence Vandalism Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

| 14. Photographs | |
|---------------------------|-------------------------------------------------------------|
| | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference | |
| CARTION | |
| CAPTION | |
| 15. Audio / Video | |
| | (related to rituals / performance / festivals etc.) |
| Reference | |
| DESCRIPTION | |
| 16. Maps/Plans/Drawings | |
| 10. Maps/Flatis/Drawlings | |
| | |
| | |
| 17. Listers | |
| NAME | NAME |
| NAME | NAME |
| 18. Reviewers | |
| NAME | NAME |
| | |
| COMMENTS | COMMENTS |