

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-189

SECTION I : IDENTIFICATION 1. Name				
Present Past Other Name (if any):	: Emarti Bai Jagnnath :	Tibara Bhawan		
2. Location				
LONGITUDE 75 ⁰ 4 ['] E	LATITUDE 28 ⁰ 13 ['] N			
Address	Chawani Bajar Tibara M	luhala Jhunjhunu		
Approach	 Village (village cod Post : Jhunjhunu State : Rajasthan It is near by Jhunjhu by regular bus servio 	District: Jhunjhunu PIN: 333001 unu Bus Stand and well connected		
3. Property Type				
Buildings Palace	Monastery	Other Structures Wall Gateway Pillar ✓ Others (specify) Bhawan		
	Open space and relatedstructuresPublic squarePark or gardenGraveyardBaolis, WellTankCave	Note: It is a ground old building having a series of circular arches at the exterior. A parapet wall having Kangura pattern adorn the top of the building. It has a boundary wall having iron-grill fittings. The exterior walls are painted green. The door lintel is aderned with intricate carving.		

4. Property Use

	ABANDONED / IN USE : ABANDONED	
Present	:	
Past	: Residance	
5. Age (Source)		
PERIOD	: 19 th century A.D.	
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
	SINGLE /MULTIPLE :	
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
✓ Architectural	Parapet wall having Kangura Pattern.	
Archaeological		
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban	
			Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:		
			(m / cm/ feet / inch	
	Number of Blocks	:	01	
	Number of Storys	:	01	
•	Spatial Organization			
	Orientation	:	The Bhawan is oriented North-south and faces the north.	
	Plan	:		
	Allocation of Spaces	:		
AF	RCHITECTURAL STYLE			
•	Ornamentation			
	Exteriors	:	Circular arch opening, door lintel has intricate carving.	
	Interiors	:		
	Movable Collections	:		
Ar	ny Other (specify)	:		
10	. Construction Technology			
	Structural System	:	Indo-Persian	
	Building Techniques	:	Arcuate	
	Material of Construction	:	Brick and stone.	

11. Condition Assessment

In General

Good / Fair

Good

Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS