



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-362

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Janki Balabh Temple  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 75° 4' E

**LATITUDE** 28° 13' N

#### **Address**

Bus stand road Ward-13

: **Village (village code)** Mukund garh  
**Post** : Mukund garh **District:** Jhunjhunu  
**State** : Rajasthan **PIN:** 333705

#### **Approach**

: The Temple is Located near Bus stand.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is a two storey structure with temple on the 2<sup>nd</sup> level approached by staircase. A large foliated arch opening frames a smaller foliated arch entrance. It has a colonnade on either side with series of foliated arches supported by pillars and a railings. It has a central courtyard. The main shrine has a Bengali done a curved chhajja.

#### 4. Property Use

---

**ABANDONED / IN USE :** In Use

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 18<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :  
**Private** :  
**Any other (Please specify)** :  
**Name** : Janki Balabh temple  
**Address** : Bus stand road mukund garh ward-13 vill. Mukundgarh P.O Mukundgarh Dist. Jhunjhunu  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 02  
Number of Storys : 02
  
- **Spatial Organization**  
Orientation : The Temple is oriented East – West and faces the West.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Foliated arches, colonnade, painting on façade.  
Medallion on spandrels  
Interiors : Courtyard, Bengali dome, carved chhajjas.  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate system
- Material of Construction** : Brick, Mortar, Plaster

### 11. Condition Assessment

---

**In General**                      **Good / Fair**  
Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

**In Brief (Attach extra sheet if necessary):**

Blackening of Surface, Peeling of plaster.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

**NAME**

**NAME**

#### **18. Reviewers**

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**