



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN - 366

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Sirolia well  
Past :  
Other Name (if any): :

#### 2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

#### Address

Kurnjee road,Ward-11

: **Village (village code)** Mukundgarh,  
**Post** : Mukundgarh **District:** Jhunjhunu  
**State** : Rajasthan **PIN:** 333705

#### Approach

: The Well is located on Kurnjee Road

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
  - Gateway
  - Pillar
  - Others (specify)
- Well**

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well✓
- Tank
- Cave

Note: It is a dug-well built on a raised platform with staircases leading to it. The face of the well is square with minars at four corners. The shaft of the minor is divided into three sections. It is surrounded by a chhajja, drums and cupole and an invorted lotus pinnacle. The face of the well is square, the shaft is octagonal and lived with brick and plaster. A stone railing over the mouth of the well connects the four minarets.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Dried up  
**Past** : Source of Drinking water

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 19<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** : Sirolia well  
**Address** : Kumjee road mukundgarh. Ward-11,village mukungarh. Po-Mukundgarh dist-Jhunjhunu  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings**  
**\* Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) :  
  
Number of Blocks :  
Number of Story's :  
  
(m / cm/ feet / inch)
  
- **Spatial Organization**  
Orientation : The well is oriented East-West and faces the West.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Four minars, stone railing over mouth of well.  
Interiors : Vertical circular shaft lined with bricks and plaster.  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo- European
- Building Techniques** : Corbelling system
- Material of Construction** : Stone, brick, mortar, plaster

### 11. Condition Assessment

---

<b>In General</b>	<b>Good / Fair</b>
-------------------	--------------------

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary):**

Blackening of surface, peeling of plaster.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

**SECTION III: REFERENCES**

**13. Reference Sources** (published and unpublished textual details)

---

**14. Photographs**

---

(Attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

**15. Audio / Video**

---

(Related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

**16. Maps/Plans/Drawings**

---

**17. Listers**

---

**NAME**

**NAME**

**18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**