



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN - 510

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Rativan Jee Ka Well  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 75° 4' E

**LATITUDE** 28° 13' N

#### **Address**

Near Rativan Jee Ki Bagiche

: **Village (village code)** Dundlod  
**Post** : Dundlod **District:** Jhunjhunu  
**State** : Rajasthan **PIN:** 333702

#### **Approach**

: The Well is situated at near Rativan Jee Ki Bagiche. It is 42 KM from Jhunjhunu and well connected by the bus services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)  
**Well**

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is a circular well cladded with rubble masonry. Water pipes are dipped inside the well for fetching water. The well rests on a raised platform. It is surrounded by octagonal pillars.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Dry  
**Past** : Source of Drinking Water

---

**5. Age (Source)**

**PERIOD** :  
**YEARS** : 18<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

---

**6. Ownership / Level of Protection**

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of :  
India / State Archaeology  
Department / Any Other (Please  
specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** : Rativan Jee Well  
**Address** : Near Rativan Jee Ki Bagiche, Ward – 14, Vill + PO –  
Dundlod,  
Dist – Jhunjhunu  
**Phone** :

---

**7. Association**

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

---

**8. Statement of Significance**

- |                                     |                     |                |
|-------------------------------------|---------------------|----------------|
| <input checked="" type="checkbox"/> | Architectural       | Brick Masonry. |
| <input type="checkbox"/>            | Archaeological      |                |
| <input type="checkbox"/>            | Historical          |                |
| <input type="checkbox"/>            | Religious           |                |
| <input type="checkbox"/>            | Any other (specify) |                |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 01  
Number of Story's : 01
  
- **Spatial Organization**  
Orientation : The Well is oriented North – South and faces the North.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : It rests on a raised platform. The well is circular in shape  
cladded with rubble masonry  
  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo Persian
- Building Techniques** : Brick Masonry
- Material of Construction** : Brick & Stone.

### 11. Condition Assessment

---

**In General** : **Good / Fair**  
Good

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

**In Brief (Attach extra sheet if necessary):**

Blackening, cracks and peeling of plaster.

## 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(Attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(Related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**