


Janpath, New Delhi -110 001, www.ignca.gov.in

### Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/JJN - 514

1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Hariram Goenka Chhatri :	
LONGITUDE 75° 4' E	<b>LATITUDE</b> 28 <sup>0</sup> 13 <sup>'</sup> N	
Address	Ward no -16, Near Rativan Jee ki Bagiche	
	: Village (village code) Post : Dundlod State : Rajasthan	Dundlod District: Jhunjhunu PIN: 333702
Approach		near Rativaj Jee ki Bagiche at m Nawalgarh and 42 KM from

## 3. Property Type



#### **ABANDONED / IN USE :** Abandoned Present Cenotaph ÷ Past Cenotaph : 5. Age (Source) PERIOD 2 18<sup>th</sup> Century A.D. YEARS 2 Precise date of Construction : Completion 2 Subsequent changes ÷ **Destruction / Demolition** ÷ 6. Ownership / Level of Protection SINGLE /MULTIPLE : Public : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private : Any other (Please specify) 2 Name : Hariram Goenka Chhatri Address Near Rativan Jee ki Bagiche, Ward - 16, Vill & PO -2 Dundlod. Dist – Jhunjhunu Phone : 7. Association WITH EVENTS • In History 2 In Rituals 2 In Building Construction 2 Any other (specify) 2 WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) 2 8. Statement of Significance

Dressed Stone.

Architectural
Archaeological
Historical
Religious
Any other (specify)

# **SECTION II: DESCRIPTION**

9.	9. Physical Description and Decorative Features		
Context Urban / Rural Setting Surroundings		* <b>Drawings</b> (Attach extra sheet if necessary) Urban	
	Cancanange		Stand in Isolation Integral part of a Landscape / Street / Complex
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Story's	:	
•	Spatial Organization Orientation	:	The Chhatri is oriented North – South and faces the North.
	Plan Allocation of Spaces	:	
<u>AF</u> •	RCHITECTURAL STYLE Ornamentation Exteriors	:	It has inverted lotus type of pinnacle. Some faded paintings can be seen on the ceiling of the chhatris.
Ar	Interiors Movable Collections <b>y Other</b> (specify)	::	

## **10. Construction Technology**

Structural System	: Indo Islamic	
<b>Building Techniques</b>	: Arcuate	
Material of Construction	: Brick & stone	

## **11. Condition Assessment**


In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

## In Brief (Attach extra sheet if necessary):

Blackening and cracks.

# 12. Threats to the Property



# **SECTION III:** REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS