INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

SECTION I: IDENTIFICATION

: Pasari House
::
:
:

LATITUDE 28° 13' N

Near Podur College, Ward-2
: Village (village code)
Post: Nawalgarh
State: Rajasthan

PIN: 333042

: The building is situated near G.B. Poddar College.

3. Property Type

1. Name

Present

2. Location

Address

Approach

Other Name (if any):

LONGITUDE 75° 4' E

Past

Buildings	Religious structures	Other Structures		
Palace	Temple	Wall		
Fort	Mosque	Gateway		
Citadel	Minar	Pillar		
Govt. building	Church	✓ Others (specify)		
Railway station	Monastery	House		
Defence building	Stupa			
Industrial building	Tomb, Mausoleum			
Other public buildings				
✓ Residential building				
Engineering structure	Open space and related	Note: It is an old house having		
	<u>structures</u>	circular arches. It is in a very		
Bridge	Public square	abysmal condition. Peeling of		
Tunnel	Park or garden	plaster, broken bricks, blackening		
Other engineering structure	Graveyard	are the common conservation		
	Baolis, Well	problem. There is an iron gate at		
	Tank	the entrance.		
	Cave			

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Residence
Past	:	Residence
5. Age (Source)		
PERIOD	•	
YEARS	:	19 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
•		SINGLE /MULTIPLE :
India / State Archaeology	:	
Department / Any Other (Please specify)		
Private		
Any other (Please specify)	:	
Name	•	Pasaria House
Address	:	Near-Podar College, Ward-2, PO Nawalgarh, Distt.
Phone	:	Jhujhun
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS	_	
Patron	•	
Architect / Engineer Any other (specify)	•	
Any other (speeny)	•	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

* **Drawings** (Attach extra sheet if necessary) Context

Urban / Rural Setting

Surroundings

Stand in Isolation

Urban

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks Number of Storys

Spatial Organization

Orientation The house is oriented east-west and faces the east.

Plan

Allocation of Spaces

ARCHITECTURAL STYLE

Ornamentation

Exterior has an iron-gate Exteriors Interiors Interior has circular arches.

Movable Collections

Any Other (specify)

10. Construction Technology

Structural System Indo-Persian **Building Techniques** Arcuvate

Material of Construction Bricks and stones.

11. Condition Assessment		
In General	Good / Fair - good	
Sign of Deterioration Serious Deterioration Danger of Disappearance	e	
In Brief (Attach extra sheet if necessary):		
Peeling of plaster, Bricks are coming out. Core material can be seen.		
12. Threats to the Property		
	✓ Natural	
	Negligence	
	Vandalism	
	Urban Pressures	

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS