



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-598

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Murarka Patnawala Bhawan  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

#### Address

Near Murarka press, Bawari Gate, Ward-28

: **Village (village code)**

**Post** : Nawalgarh

**District**: Jhunjhunu

**State** : Rajasthan

**PIN**: 333042

#### Approach

: The building is situated at Nawalgarh, 32 km from Jhunjhun Bus stand.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)  
Bhawan

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is an old building having foliated arch opening. The parapet walls on the top of the building. The side walls are dilapidated. The interior has many circular arches. The building is abandoned. The interior has double pillars.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Residence  
**Past** : Residence

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 20<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** : Murarka patna wala  
**Address** : Bawari Gate, Murarka Pressi, Ward 28, PO Nawalgarh, Distt Jhunjhun.  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - ✓ **Any other (specify)** : Used for fetching water.
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |                |
|-------------------------------------|---------------------|----------------|
| <input checked="" type="checkbox"/> | Architectural       | Drerred stone. |
| <input type="checkbox"/>            | Archaeological      |                |
| <input type="checkbox"/>            | Historical          |                |
| <input type="checkbox"/>            | Religious           |                |
| <input type="checkbox"/>            | Any other (specify) |                |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The bhawan is oriented east-west and faces the West.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : The walls are partially damaged. It has cusped arches at the entrance.  
Interiors : The interior has many rooms and circular arches.  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate
- Material of Construction** : Brick and stone.

## 11. Condition Assessment

---

**In General**

**Good / Fair - good**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

### **In Brief (Attach extra sheet if necessary):**

Blackening of the surface, exposed bricks and delipidated.

## 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**