



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-607

SECTION I : IDENTIFICATION

1. Name

Present : Mohanlal Murark putna ki haveli
Past :
Other Name (if any): :

2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

Address

Near Chokhani Gas Agency, Bawari Gate, Ward 28

: **Village (village code)**

Post : Nawalgarh

District: Jhunjhunu

State : Rajasthan

PIN: 333042

Approach

: The haveli is situated near Bawari Gate at Nawalgarh, 32 km from Jhunjhun Bus stand.

3. Property Type

Buildings

- | | |
|-------------------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input checked="" type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|-------------------------------------|----------------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input checked="" type="checkbox"/> | Others (specify)
Haveli |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: It is a huge structure in a ruined state at the exterior. The foliated arches and chhajjas supported by stone brackets resembles with the Indo-Persian style of architecture. The interior of the building has a profusion of colourful and delicate Rajasthani fresco. The door has intricate carvings and vault of the arches are adorned with floral designs..

4. Property Use

ABANDONED / IN USE : In use

Present : Residence
Past : Residence

5. Age (Source)

PERIOD :
YEARS : 19th Century A.D.
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :
Private :
Any other (Please specify) :
Name : Mohanlal Murarka Putna
Address : Near Chokhani Gas Agency, Bawari Gate, Ward-28, PO Nawalgarh, Distt. Jhunjhun
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - ✓ **Any other (specify)** : Being used for residential purposes

8. Statement of Significance

- | | | |
|-------------------------------------|---------------------|----------------|
| <input checked="" type="checkbox"/> | Architectural | Drerred stone. |
| <input type="checkbox"/> | Archaeological | |
| <input type="checkbox"/> | Historical | |
| <input type="checkbox"/> | Religious | |
| <input type="checkbox"/> | Any other (specify) | |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * **Drawings** (Attach extra sheet if necessary)
- Urban / Rural Setting** : Urban
- Surroundings** : **Stand in Isolation**
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)
- Number of Blocks : 02
- Number of Storys : 01

- **Spatial Organization**
Orientation : The Haveli is oriented North-South and faces the South
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : It has foliated arch at the entrance having faded wall paintings.
Interiors : The interior has profusion of paintings but the structure is in semi-ruined condition.
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo-Parsian
- Building Techniques** : Arcuate
- Material of Construction** : Brick and Stone

11. Condition Assessment

In General

Good / Fair – good

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Peeling of plasters, exposed bricks and discolouration.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS