



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-695

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Govindram Damodar Sekhasaria Haveli  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

#### Address

Near Jangid Hospital, Nanshah Gate Ward-12

: **Village (village code)**

**Post** : Nawalgarh

**District**: Jhunjhunu

**State** : Rajasthan

**PIN**: 333042

#### Approach

: It is 40km from Jhunjhunu. It is well connected by regular bus and train services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)

Haveli

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is a huge Masonic structure having projected balconies supported by stone-brackets. It has a pointed arch opening. A parapet wall is adorned with Kangura pattern. The door at the entrance is painted blue.

#### 4. Property Use

---

**ABANDONED / IN USE : IN USE**

**Present** : Residence  
**Past** : Residence

#### 5. Age (Source)

---

**PERIOD** : 18<sup>th</sup> century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** : Govindram Damodar Sekhasaria  
**Address** : Near Jangid Hospital Nanshah Gate. Ward-12, P.O.- Nawalgarh. Dist-Jhunjhunu  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |  |
|-------------------------------------|---------------------|--|
| <input checked="" type="checkbox"/> | Architectural       | Parapet wall on top of the haveli is of Kangura Pattern. |
| <input type="checkbox"/>            | Archaeological      |  |
| <input type="checkbox"/>            | Historical          |  |
| <input type="checkbox"/>            | Religious           |  |
| <input type="checkbox"/>            | Any other (specify) |  |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context** : \* **Drawings** (Attach extra sheet if necessary)  
**Urban / Rural Setting** : Urban  
**Surroundings** : **Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
Number of Blocks : 02  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The haveli is oriented east-west and faces the west.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Pointed arch at the entrance adorned with beautiful Rajasthani frescos.  
Interiors : A series of foliated arches having Rajasthani frescos adorn the interior.  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate
- Material of Construction** : Brick and stone.

### 11. Condition Assessment

---

In General	Good / Fair	Good
------------	-------------	------

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

**In Brief (Attach extra sheet if necessary):**

Blackening.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

##### **NAME**

##### **NAME**

#### **18. Reviewers**

##### **NAME**

##### **NAME**

##### **COMMENTS**

##### **COMMENTS**