

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-749

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	: Bank of Baroda :
2. Location	
LONGITUDE 75° 4' E	LATITUDE 28 ⁰ 13 ['] N
Address	Ward No.5
	: Village (village code) Alsisar Post : Alsisar District: Jhunjhunu State : Rajasthan PIN: 331025
Approach	: The Bank is situated at Alsisar near by Bus stand
3. Property Type	
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Other Structures Temple Wall Mosque Gateway Minar Pillar Church ✓ Monastery Bank Stupa Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote: The office of bank of baroda has occupied a beautiful building with Indo-European architecture. Raised on a high platform can be accessed through circularly planned stairs. Has pillard porch at entrance with a balcony over it. The facado and railing of this balcony is of jari screens along with the terrace railing which also has a foliated cresting. Has a boundary wall all around.

4. Property Use					
	ABANDONED / IN USE : In use				
Present Past	: Bank : Private home (Residence)				
5. Age (Source)					
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	20 th Century A.D.				
6. Ownership / Level of Protection					
	SINGLE /MULTIPLE :				
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address	: : : : Ward 5, Vill & PO Alsisar Distt Jhunjhun,State Rajasthan				
Phone	:				
7. Association					
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 					
8. Statement of Significance					
Architectural Archaeological Historical Religious					

Any other (specify)

SECTION II: DESCRIPTION

	* Drawings (Attach extra sheet if necessary) Urban	
	Stand in Isolation Integral part of a Landscape / Street / Complex	
:	(m / cm/ feet / inch)	
:	02 01	
:	The Bank is oriented East-West and faces -West	
:	The façade has restorn like reliefs with similar carvings.	

Structural System	:	Indo-Persian
Building Techniques Material of Construction		Corbelled Stone, bricks, lime, cement etc.
	•	Stone, bricks, lime, cement etc.

11. Condition Assessment

In General

Good / Fair - good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Staining and blackening- else well rept.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS