

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No. 775

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Banarilal Sankari ka haveli :	
LONGITUDE 75 ⁰ 4 ['] E	LATITUDE 28 ⁰ 13 [°] N	
A5ddress	Ward No.	
	: Village (village code) Malsisar Post : Malsisar District: Jhunjhunu State : Rajasthan PIN: 331028	
Approach	: The haveli is situated at Malsisar village in ward no.5 which is 32 km far from Jhunjhun and well connected by private and govt buses.	

3. Property Type

 Buildings	Religious structures	Other Structures
Palace	Temple	Wall
Fort	Mosque	Gateway
Citadel	Minar	Pillar
Govt. building	Church	✓ Others (specify)
Railway station	Monastery	Haveli
Defence building	Stupa	
Industrial building	Tomb, Mausoleum	
Other public buildings		
Desidential building		
Residential building		
Engineering structure	Open space and related	Note: This complex has heavy
 Engineering structure	structures	lofty nibble boundary with an iron
Engineering structure Bridge	<i>structures</i> Public square	lofty nibble boundary with an iron gate. It is a single floored but a
Engineering structure Bridge Tunnel	structures Public square Park or garden	lofty nibble boundary with an iron gate. It is a single floored but a high ceiling structure again with
Engineering structure Bridge	structures Public square Park or garden Graveyard	lofty nibble boundary with an iron gate. It is a single floored but a high ceiling structure again with thick walls. Has a foliated arched
Engineering structure Bridge Tunnel	structures Public square Park or garden	lofty nibble boundary with an iron gate. It is a single floored but a high ceiling structure again with thick walls. Has a foliated arched opening with a bracket supported
Engineering structure Bridge Tunnel	structures Public square Park or garden Graveyard	lofty nibble boundary with an iron gate. It is a single floored but a high ceiling structure again with thick walls. Has a foliated arched
Engineering structure Bridge Tunnel	structures Public square Park or garden Graveyard Baolis, Well	lofty nibble boundary with an iron gate. It is a single floored but a high ceiling structure again with thick walls. Has a foliated arched opening with a bracket supported

4. Property Use

		ABANDONED / IN USE : Abandoned
Present Past	:	Residential
5. Age (Source)		
PERIOD	:	
YEARS	÷	19 th Century A.D.
Precise date of Construction		
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	Ward No. 5, Vill & PO Malsisar Distt Jhunjhun, State Rajasthan
Phone	:	Najastian
7. Association		
WITH EVENTS		
In History		
In Rituals	:	
In Building Construction		
Any other (specify)		
WITH PERSONS		
Patron		
Architect / Engineer		
Any other (specify)	÷	
	-	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		

Any other (specify)

SECTION II: DESCRIPTI	ON
------------------------------	----

 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary) Rural
		Stand in Isolation Integral part of a Landscape / Street / Complex
• Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch
Number of Blocks	:	01
Number of Storys	:	01
Spatial Organization		
Orientation	÷	The haveli is oriented East-West and faces West.
Plan Allocation of Spaces	:	
ARCHITECTURAL STYLE		
Ornamentation		
Exteriors	:	Small windows opening on the side walls.
Interiors	÷	
Movable Collections		
Any Other (specify)	•	
10. Construction Technology		

Structural System	:	Indo-Persian
Building Techniques	:	Arcuate
Material of Construction		Stone, rubble, cementing materials etc.

11. Condition Assessment

In General

Good / Fair - good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

The boundary wall has lost its plaster, opening the masonry, discoloration, blackening etc.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS