



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-816

SECTION I : IDENTIFICATION

1. Name

Present : Mano Singhania ka Well
Past :
Other Name (if any): :

2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

Address

Ward-13

: **Village (village code)** Bissna
Post : Bissna **District:** Jhunjhunu
State : Rajasthan **PIN:** 331027

Approach

: It is 40km from Jhunjhunu & well connected to regular bus services and train services

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)
Well

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: Raised on a high platform the well has two lofty towers close to its rim to support its pully device. The two towers are plastered and connected to each other with a hollow space in the middle.

4. Property Use

ABANDONED / IN USE : Abandoned

Present : Dried up
Past : Source of Drinking water

5. Age (Source)

PERIOD :
YEARS : 20th Century A.D.
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :
Private :
Any other (Please specify) :
Name :
Address : Ward No-13, Vil + P.O. - Bissna, Dist- Jhunjhunu,, State- Rajasthan
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * **Drawings** (Attach extra sheet if necessary)
Urban / Rural Setting : Urban
Surroundings : **Stand in Isolation**
: **Integral part of a Landscape / Street / Complex**

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)
Number of Blocks :
Number of Storys :

- **Spatial Organization**
Orientation : The Well is oriented North-South & Faces the South.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : No ornamentation
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo- Persian
Building Techniques : Arcuate
Material of Construction : Stone, Rubble masonry, Lime Plaster etc.

11. Condition Assessment

In General **Good / Fair**
 Good

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary)

The plinth has lost major portions, exposing the rubbles victim to graffiti and maintenance wild growth, blackening, peeling of plaster.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS