



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-820

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Rajasthan Public School  
**Past** : Bishan Singhjee Ka Chhatri  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 75° 4' E

**LATITUDE** 28° 13' N

#### Address

Near- Bus Stand, Ward No. 12

**Village (village code)** Bissna  
**Post** : Bissna **District:** Jhunjhunu  
**State** : Rajasthan **PIN:** 331027

#### Approach

: It is 40km from Jhunjhunu & well connected to regular bus services and train services

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)  
School

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** Raised an very high platforms this chattri complex has been planned & exempted beautifully. It has small chattris with vaulted caporal roofing & round domical roofing chattri'sall around. In the centre there is a big chattri in octagonal plan with domical roofs.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : School  
**Past** : Chhattri

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 20<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** : Ward No-12, Vill. + P.O. - Bissan, Dist- Jhunjhunu,, State- Rajasthan  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context** : \* **Drawings** (Attach extra sheet if necessary)  
**Urban / Rural Setting** : Urban  
**Surroundings** : **Stand in Isolation**  
: **Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
Number of Blocks :  
Number of Storys :
  
- **Spatial Organization**  
Orientation : The School is oriented East- West & Faces the West  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : The ruminants of the paintings indicate human fig., birds & animals were also painted.  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo – Persian
- Building Techniques** : Arcuate
- Material of Construction** : Stone, Lime Plaster, Rubble, etc.

### 11. Condition Assessment

---

In General	Good / Fair
------------	-------------

Good

- |                                     |                         |
|-------------------------------------|-------------------------|
| <input type="checkbox"/>            | Sign of Deterioration   |
| <input checked="" type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/>            | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary)**

It needs urgent attention. The painted layers have largely disappeared.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input checked="" type="checkbox"/> | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input checked="" type="checkbox"/> | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**