



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-842

SECTION I : IDENTIFICATION

1. Name

Present : Sushil Kumar jee Joshi ka Haveli
Past :
Other Name (if any): :

2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

Address

Ward No. 16, House No. 79

: **Village (village code)** Bissan
Post : Bissan **District:** Jhunjhunu
State : Rajasthan **PIN:** 331027

Approach

: It is 40 k.m. from Jhunjhunu and it is well connected by bus and train services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)
Haveli

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: This is a pretentiously painted building raised on a high platform & surrounded by a boundary wall. It has a high-rise foliated arched gateway with a profusely carved wooden door & lintel. There is a perpendicular expansion in the right hand side with similar architecture. It seems to be a high ceiling building with a adorned façade.

4. Property Use

ABANDONED / IN USE : In use

Present : Residential
Past : Residence

5. Age (Source)

PERIOD :
YEARS : 20th Century A.D.
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name : Ward No. 16, House No. 79, Vill. + P.O. Bissan, Distt. Jhunjhunu, State : Rajasthan
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban / Rural Setting
Surroundings : * **Drawings** (Attach extra sheet if necessary)
Rural Setting Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)

Number of Blocks : 02
Number of Storys : 01

- **Spatial Organization**
Orientation : The Haveli is oriented East-West and faces East
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Near the gateway there are full size paintings of guards with Indian faces but European attire including boots. The colours used are Red, Ocher, green, blue, black, white, grey etc.

Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate
- Material of Construction** : Stone, Rubble, Bricks, Lime Cement, etc.

11. Condition Assessment

| In General | Good / Fair |
|-------------------|--------------------|
|-------------------|--------------------|

Good

- | | |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Many painted portions have lost their vibrancy. Have been inappropriately renovated. Lack of general maintenance.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input checked="" type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input checked="" type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS