



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-917

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Vinod Prasad ki Haveli  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

#### Address

Ward No – 10

: **Village (village code)** Bissan  
**Post** : Bissan **District:** Jhunjhunu  
**State** : Rajasthan **PIN:** 331027

#### Approach

: It is 40km from Jhunjhunu & well connected to regular bus services and train services

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Haveli**

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is a Building with intricate wood carving or the wall and beautiful wall painting. This double L – shaped building is having dominant elements of Indo – Persian style

#### 4. Property Use

---

**ABANDONED / IN USE :** In Use

**Present** : Residence  
**Past** : Resicidence

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 20<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) : Privately Owned  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** : Ward No.- 10, vill+po – Bissan, Dist.- Jhunjhunu, Rajasthan.  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** : In History
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

<input type="checkbox"/>	Architectural	Architectural
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	Historical
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Rural Setting Surroundings  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The Haveli is oriented East- West & Faces the East.  
Plan : Double L- Shaped  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Multifoliated arch's resting on carved pillars, brackets, jail, structures and long doors frames give it an aristocrats look.  
  
Interiors : Walls painted with floral designs.  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Brick mortar. Indo Persian style
- Building Techniques** : Beautiful blending of Mughal architect. Arcuate system
- Material of Construction** : Brick, Cement, Sand, wood

### 11. Condition Assessment

---

In General	Good / Fair
------------	-------------

Good

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary)**

Algal problems here and there and discolourisation of the paintings on the wall

## 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

##### **NAME**

##### **NAME**

#### **18. Reviewers**

##### **NAME**

##### **NAME**

##### **COMMENTS**

##### **COMMENTS**