



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-965

SECTION I : IDENTIFICATION

1. Name

Present : Kali kamala ka Bhawan
Past :
Other Name (if any): :

2. Location

LONGITUDE 75° 4' E

LATITUDE 28° 13' N

Address

Ward No.18

: **Village (village code)** Bissar
Post : Bissar **District:** Jhunjhunu
State : Rajasthan **PIN:** 331027

Approach

: It is 40 km from Jhunjhun and it is well connected by regular bus and train services

3. Property Type

Buildings

- | | |
|-------------------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input checked="" type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|-------------------------------------|----------------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input checked="" type="checkbox"/> | Others (specify)
Bhawan |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|-------------------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input checked="" type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: It is a two storeyed building of 16th century AD on a raised platform and with a cloistered verandah. Some later additions in the building is quite evident.

4. Property Use

ABANDONED / IN USE : Abandoned

Present :
Past : Residential

5. Age (Source)

PERIOD :
YEARS : 16th Century A.D.
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private : not protected
Any other (Please specify) :
Name : Ward No.18, Vill & PO Bissar, Distt Jhunjhun State: Rajasthan
Address :
Phone :

7. Association

- **WITH EVENTS**
 - ✓ **In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|-------------------------------------|---------------------|
| <input type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input checked="" type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * **Drawings** (Attach extra sheet if necessary)
Urban / Rural Setting : Rural
Surroundings : **Stand in Isolation**
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)

Number of Blocks : 02
Number of Storys : 01

- **Spatial Organization**
Orientation : The bhawan is oriented North-South and faces North
Plan : Rectangular
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : A cloistered verandah in the ground floor of the building situated on a raised platform.
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Masonary, Indo-Islamic elements evident
- Building Techniques** : Corbelling system
- Material of Construction** : Wood, brick, rod, mortar

11. Condition Assessment

In General **Good / Fair – Good**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Deplastering, crack, decolourisation are noticed.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS