



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-968

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Mayturam jee ka haveli  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 75° 4' E

**LATITUDE** 28° 13' N

#### Address

Ward No.11

: **Village (village code)** Bissar  
**Post** : Bissar **District:** Jhunjhunu  
**State** : Rajasthan **PIN:** 331027

#### Approach

: It is 40 km from Jhunjhun and it is well connected by regular bus and train services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)  
Haveli

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is a building is on a raised platform with stairs. Wall painting cusped shaped arch, arcade, high relief on the walls brackets are used as decongestive elements.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Residential  
**Past** : Residential

#### 5. Age (Source)

---

**PERIOD** : 19<sup>th</sup> Century AD  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of  
India / State Archaeology  
Department / Any Other (Please  
specify)

**Private** : not protected

**Any other (Please specify)** :

**Name** : Ward No.11, Vill & PO Bissar, Distt Jhunjhun State:  
Rajasthan

**Address** :

**Phone** :

#### 7. Association

---

• **WITH EVENTS**

✓ **In History** :

**In Rituals** :

**In Building Construction** :

**Any other (specify)** :

• **WITH PERSONS**

✓ **Patron** : Magturanjee

**Architect / Engineer** :

**Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |
|-------------------------------------|---------------------|
| <input type="checkbox"/>            | Architectural       |
| <input type="checkbox"/>            | Archaeological      |
| <input checked="" type="checkbox"/> | Historical          |
| <input type="checkbox"/>            | Religious           |
| <input type="checkbox"/>            | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Rural  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The haveli is oriented East-West and faces West  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Intricate wall painting, brackets, cusped arched entrance, arcade as usual. Decorated doors with the door frame is also noticed.  
  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Masonary, Indo-Islamic and European elements.
- Building Techniques** : Corbelling as the major technique with arcuate technique in selected areas.
- Material of Construction** : Brick, mortar,

### 11. Condition Assessment

---

**In General**                      **Good / Fair – Good**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

#### **In Brief (Attach extra sheet if necessary):**

Wrong treatment, plaster loss, painting loss, fading and abrasion in the paid area.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input checked="" type="checkbox"/> | Negligence      |
| <input checked="" type="checkbox"/> | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**