

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-980

<u>SE</u> 1. Name	ECTION I : IDENTIFICATION	
Present Past Other Name (if any):	: Laksha ram Buchesia : :	ka well
2. Location		
LONGITUDE 75° 4' E	LATITUDE 28 ⁰ 13 ['] N	
Address	Church Road, Bissar	
Approach	: Village (village code) Post : Bissar State : Rajasthan : It is 40 km from Jhun	Bissar District: Jhunjhunu PIN: 331027 jhun and it is well connected by
, .pp. 0 4011	regular bus and train s	
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify) Well
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic square Park or gardenGraveyard✓Baolis, Well Tank Cave	Note: It is an old well. The well is on an elevated platform and is of rounded shape. The four corners of the well is occupied by four octagonal minars with decorated superstructure of chajja, drum, dom, inverted lotus and pinnacle.

4. Property Use

		ABANDONED / IN USE : Abandoned
Present Past	:	Sources of Drinking water
5. Age (Source)		
PERIOD	:	19 th Century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protectio	n	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private	:	not protected
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
✓ In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
✓ Patron	:	Laksho Ram Buchesia ka well
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		

Architectural
 Archaeological
 ✓ Historical
 Religious
 Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features * **Drawings** (Attach extra sheet if necessary) Context **Urban / Rural Setting** Rural Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex ✓ Quantification Area Dimension $(L \times B \times H)$: (m / cm/ feet / inch) Number of Blocks ÷ Number of Storys : **Spatial Organization** Orientation The well is oriented North-South and faces the South 1 Plan Round shaped on a rectangular plinth : Allocation of Spaces **ARCHITECTURAL STYLE** Ornamentation Octagonal minars with octagonal chajja, drum, dome and Exteriors ÷ inverted lotus with pinnacle. Interiors **Movable Collections** : **Any Other** (specify) Situated on an elevated platform and the old pulley is 2 noticed. **10. Construction Technology** Structural System : Masonary, **Building Techniques** Corbelling :

Material of Construction **11. Condition Assessment**

In General

Good / Fair - Good

2

Brick, cement, metal

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

The well is maintained quite well.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attach list as in page 6 in some of multiple shots much s)
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS