



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JLR-116

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Shree Madho Singh ki Chhatri  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 73° 5' 33"E

**LATITUDE** 25° 48' 37" N

#### **Address**

Main Bazar Bhadrajun, Jalor

: **Village (village code)** Bhadrajun  
**Post** : Bhadrajun **District:** Jalor  
**State** : Rajasthan **PIN:** 307031

#### **Approach**

: The Chhatri is situated at Bhadrajun in Jalor. It is 54 km. away from Jalor district. It is well connected by regular bus services.

#### 3. Property Type

##### **Buildings**

- ☐ Palace
- ☐ Fort
- ☐ Citadel
- ☐ Govt. building
- ☐ Railway station
- ☐ Defence building
- ☐ Industrial building
- ☐ Other public buildings
- ☐ Residential building

##### **Religious structures**

- ☐ Temple
- ☐ Mosque
- ☐ Minar
- ☐ Church
- ☐ Monastery
- ☐ Stupa
- ☐ Tomb, Mausoleum

##### **Other Structures**

- ☐ Wall
- ☐ Gateway
- ☐ Pillar
- ☒ Others (specify)  
**Chhatri**

##### **Engineering structure**

- ☐ Bridge
- ☐ Tunnel
- ☐ Other engineering structure

##### **Open space and related structures**

- ☐ Public square
- ☐ Park or garden
- ☐ Graveyard
- ☐ Baolis, Well
- ☐ Tank
- ☐ Cave

**Note:** This highly embellished chhatri with multiple jharokhas. There small domical (oblong) structures surrounding the main dome. It has foliage decoration with arches.

#### 4. Property Use

---

**ABANDONED / IN USE :** Abandoned

**Present** : Memorial  
**Past** : Memorial

#### 5. Age (Source)

---

**PERIOD** : 16<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of  
India / State Archaeology  
Department / Any Other (Please  
specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** : Canotaph
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |                              |
|-------------------------------------|---------------------|------------------------------|
| <input checked="" type="checkbox"/> | Architectural       |                              |
| <input type="checkbox"/>            | Archaeological      |                              |
| <input type="checkbox"/>            | Historical          |                              |
| <input type="checkbox"/>            | Religious           |                              |
| <input type="checkbox"/>            | Any other (specify) | Chhatri having multiple dome |

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings**  

\* **Drawings** (Attach extra sheet if necessary)  
Rural Setting Surroundings

**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
- **Quantification**  
Area Dimension ( L x B x H) :  

(m / cm/ feet / inch)

  
Number of Blocks : 01  
Number of Storys : 01
- **Spatial Organization**  
Orientation : The Chhatri is oriented East-West and faces the East  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors : Decorated parapet  
Interiors : Colonnade platform  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

- |                                 |   |                |
|---------------------------------|---|----------------|
| <b>Structural System</b>        | : | Indo Persian   |
| <b>Building Techniques</b>      | : | Arcuate        |
| <b>Material of Construction</b> | : | Stone, Plaster |

### **11. Condition Assessment**

---

<b>In General</b>	<b>Good / Fair</b>
	Good

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

**In Brief (Attach extra sheet if necessary):**

Algae on the dome.

## 12. Threats to the Property

---

<input checked="" type="checkbox"/>	Natural
<input type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**