



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JLR-149

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Mahaveer Swami jee Mandir  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 73° 5' 33"E

**LATITUDE** 25° 48' 37" N

#### **Address**

Nandishwar Deewp Tirth, Jalor, Infront of Collectrate, Jalor

: **Village (village code)**

**Post** : Jalor

**District**: Jalor

**State** : Rajasthan

**PIN**: 343001

#### **Approach**

: The Temple is situated at Jalor city. It is 1 km. away from Jalor bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### **Buildings**

- ☐ Palace
- ☐ Fort
- ☐ Citadel
- ☐ Govt. building
- ☐ Railway station
- ☐ Defence building
- ☐ Industrial building
- ☐ Other public buildings
- ☐ Residential building

##### **Religious structures**

- ☒ Temple
- ☐ Mosque
- ☐ Minar
- ☐ Church
- ☐ Monastery
- ☐ Stupa
- ☐ Tomb, Mausoleum

##### **Other Structures**

- ☐ Wall
- ☐ Gateway
- ☐ Pillar
- ☐ Others (specify)

##### **Engineering structure**

- ☐ Bridge
- ☐ Tunnel
- ☐ Other engineering structure

##### **Open space and related structures**

- ☐ Public square
- ☐ Park or garden
- ☐ Graveyard
- ☐ Baolis, Well
- ☐ Tank
- ☐ Cave

**Note:** This is a multistoried tower based temple. It has colourfully decorated carved dwarf-pales and elephants in the entrance way. It has decorated parapet with chhajja. It has perforated work sidewall surrounding the whole pillared hall. It has pyramidal roof structures on the roof. It has highly embellished shrine hall.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 20<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) : Nandishwar Dweep Tirth (Jain trust, Jalor) (Rajasthan)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** : Living temple
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

<input checked="" type="checkbox"/>	Architectural	
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	Temple with multistoried tower.

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings**  

**\* Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
- **Quantification**  
Area Dimension ( L x B x H) :  

(m / cm/ feet / inch)

  
Number of Blocks : 01  
Number of Storys : 01
- **Spatial Organization**  
Orientation : The Temple is oriented East-West and faces the West  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors : Pyramidal roof structures  
Interiors : Main shrine is placed in a small chhatri with dome  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

- |                                 |   |                |
|---------------------------------|---|----------------|
| <b>Structural System</b>        | : | Nagara style   |
| <b>Building Techniques</b>      | : | Trabeate       |
| <b>Material of Construction</b> | : | Stone, Plaster |

### **11. Condition Assessment**

---

<b>In General</b>	<b>Good / Fair</b>
	Good

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

**In Brief (Attach extra sheet if necessary):**

## 12. Threats to the Property

---

<input type="checkbox"/>	Natural
<input type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**