



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JLR-171

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Rupeshwar Mahadev Mandir  
Past :  
Other Name (if any): :

#### 2. Location

**LONGITUDE** 73° 5' 33"E

**LATITUDE** 25° 48' 37" N

**Address**

Chandinath Mahadev Mandir, Bhinmal, Jalor,

: **Village (village code)**

**Post** : Bhinmal

**District**: Jalor

**State** : Rajasthan

**PIN**: 303429

**Approach**

: The Temple is situated at Bhinmal in Jalor. It is 72 km. away from Jalor district. It is well connected by regular bus services.

#### 3. Property Type

##### **Buildings**

- ☐ Palace
- ☐ Fort
- ☐ Citadel
- ☐ Govt. building
- ☐ Railway station
- ☐ Defence building
- ☐ Industrial building
- ☐ Other public buildings
- ☐ Residential building

##### **Religious structures**

- ☒ Temple
- ☐ Mosque
- ☐ Minar
- ☐ Church
- ☐ Monastery
- ☐ Stupa
- ☐ Tomb, Mausoleum

##### **Other Structures**

- ☐ Wall
- ☐ Gateway
- ☐ Pillar
- ☐ Others (specify)

##### **Engineering structure**

- ☐ Bridge
- ☐ Tunnel
- ☐ Other engineering structure

##### **Open space and related structures**

- ☐ Public square
- ☐ Park or garden
- ☐ Graveyard
- ☐ Baolis, Well
- ☐ Tank
- ☐ Cave

**Note:** This stupendous temple has double pidadeul with steps and chhajja. It has decorated parapet, creeper carvings on the pillars and cure carved baby elephants. It has serpentine arches. It has various carved figurines with capital of the broken pillars are spread outside the temple complex. It has a stone carved Lingam.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 17<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE / MULTIPLE :**

**Public** : Archaeological Survey of  
India / State Archaeology  
Department / Any Other (Please  
specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** : Living temple
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |                            |
|-------------------------------------|---------------------|----------------------------|
| <input checked="" type="checkbox"/> | Architectural       |                            |
| <input type="checkbox"/>            | Archaeological      |                            |
| <input type="checkbox"/>            | Historical          |                            |
| <input type="checkbox"/>            | Religious           |                            |
| <input type="checkbox"/>            | Any other (specify) | Temple with pyramidal roof |

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings**  

**\* Drawings** (Attach extra sheet if necessary)  
Rural Setting Surroundings  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
- **Quantification**  
Area Dimension ( L x B x H) :  

(m / cm/ feet / inch)

Number of Blocks

:

01

Number of Storys

:

01
- **Spatial Organization**  
Orientation : The Temple is oriented North-South and faces the North  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors : Creeper decoration on the pillar  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

<b>Structural System</b>	:	Nagara style
<b>Building Techniques</b>	:	Trabeate
<b>Material of Construction</b>	:	Stone, plaster

### **11. Condition Assessment**

---

<b>In General</b>	<b>Good / Fair</b>
	Good

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

**In Brief (Attach extra sheet if necessary):**

## 12. Threats to the Property

---

<input type="checkbox"/>	Natural
<input type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**