



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JLR-223

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Sunda Mata Mandir  
Past :  
Other Name (if any): :

#### 2. Location

LONGITUDE 73° 5' 33"E

LATITUDE 25° 48' 37"N

#### Address

Sunda Parwat

: **Village (village code)**

**Post** : Rajapura

**District**: Jalor

**State** : Rajasthan

**PIN**: 303429

#### Approach

: The Temple is situated at Sunda Parwat in Jalor. It is 100 k.m. away from Jalor Distt. It is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- ☐ Palace
- ☐ Fort
- ☐ Citadel
- ☐ Govt. building
- ☐ Railway station
- ☐ Defence building
- ☐ Industrial building
- ☐ Other public buildings
- ☐ Residential building

##### *Religious structures*

- ☒ Temple
- ☐ Mosque
- ☐ Minar
- ☐ Church
- ☐ Monastery
- ☐ Stupa
- ☐ Tomb, Mausoleum

##### *Other Structures*

- ☐ Wall
- ☐ Gateway
- ☐ Pillar
- ☐ Others (specify)

##### *Engineering structure*

- ☐ Bridge
- ☐ Tunnel
- ☐ Other engineering structure

##### *Open space and related structures*

- ☐ Public square
- ☐ Park or garden
- ☐ Graveyard
- ☐ Baolis, Well
- ☐ Tank
- ☐ Cave

**Note:** This is a multistoreyed pyramidal roof based temple with elevations. It can be reached through staircases. It has a beautiful gateway with semi-circular arch and carved pillars. It has pillared hall with brackets. It has carved dwarfals on the doorway. It has colourful animal and human carvings in front of the entrance way.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 17<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** : Shree Chamunda Mata Trust Sunda Parwat.  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** : Living temple
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

<input checked="" type="checkbox"/>	Architectural	
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	Temple with Pyramidal roof

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings**  

**\* Drawings** (Attach extra sheet if necessary)  
Rural Setting Surroundings  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) :  

(m / cm/ feet / inch)

Number of Blocks

:

01

Number of Storys

:

01
  
- **Spatial Organization**  
Orientation : The Temple is oriented East/West and faces the East  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors : Dome Elevations  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

<b>Structural System</b>	:	Nagara Style
<b>Building Techniques</b>	:	Trabeate
<b>Material of Construction</b>	:	Stone, Plaster

### **11. Condition Assessment**

---

<b>In General</b>		<b>Good / Fair</b>
		Good

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

**In Brief (Attach extra sheet if necessary):**

## 12. Threats to the Property

---

<input type="checkbox"/>	Natural
<input type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**