

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JSL-003

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any):	: Baba Ram Dev ji ka Mandir :	
2. Location		
LONGITUDE 72 ⁰ 20 ['] E	LATITUDE 28 ⁰ 02 ['] N	
Address	Sonargarh, Jaisalmer	
	: Village (village code) Post : Gopa Chowk District: Jaisalmer State : Rajasthan PIN: 345001	
Approach	 The Mandir is situated at Sonargarh, Jaisalmer. It is 2 k.m. away from Bus Stand Jaisalmer Distt. It is well connected by regular bus services. 	

3. Property Type

 Buildings		Religious structures		Other Structures
Palace	\checkmark	Temple		Wall
Fort		Mosque		Gateway
Citadel		Minar		Pillar
Govt. building		Church		Others (specify)
Railway station		Monastery		
Defence building		Stupa		
Industrial building		Tomb, Mausoleum		
Other public buildings				
Residential building				
Engineering structure	•	en space and related uctures		te: This temple is made up on vated platform with upraised
	stru	ictures	elev	te: This temple is made up on vated platform with upraised rcases. It has pointed arch
 <i>Engineering structure</i> Bridge Tunnel	stru	•	elev stai	vated platform with upraised
Bridge	stru	<i>ictures</i> Public square	elev stai ope dec	vated platform with upraised rcases. It has pointed arch ening at entrance, spendral is corated with floral pattern. Two
Bridge Tunnel		ictures Public square Park or garden	elev stai ope dec scu	vated platform with upraised rcases. It has pointed arch ening at entrance, spendral is corated with floral pattern. Two lptures of horse at the top.
Bridge Tunnel		ictures Public square Park or garden Graveyard	elev stai ope dec scu Insi	vated platform with upraised rcases. It has pointed arch ening at entrance, spendral is corated with floral pattern. Two lptures of horse at the top. de it has foliated arch opening.
Bridge Tunnel		ictures Public square Park or garden Graveyard Baolis, Well	elev stai ope dec scu Insi Wir	vated platform with upraised rcases. It has pointed arch ening at entrance, spendral is corated with floral pattern. Two lptures of horse at the top. de it has foliated arch opening. ndows are decorated with
Bridge Tunnel		ictures Public square Park or garden Graveyard Baolis, Well Tank	elev stai ope dec scu Insi Wir latti	vated platform with upraised reases. It has pointed arch ening at entrance, spendral is corated with floral pattern. Two lptures of horse at the top. de it has foliated arch opening. ndows are decorated with

4. Property Use

		ABANDONED / IN USE : In use
Present	:	Religious
Past	:	
5. Age (Source)		
PERIOD	:	19 th Century A.D.
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	A.S.I
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify) Name	:	
Address	÷	
Phone	:	
	•	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	•	
WITH PERSONS		
Patron	•	Tampla
Architect / Engineer Any other (specify)	:	Temple
Any other (specify)	•	
8. Statement of Significance		
Architectural		
Archaeological		

Archaeological Historical Religious Any other (specify)

Foliated arch

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Mandir is oriented East-West and faces the East	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:	Foliated arch, pointed arch	

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Trabeate System
Material of Construction	:	Stone and Plaster

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS