

**INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS** 

Janpath, New Delhi -110 001, www.ignca.gov.in

### Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/JSL-041

1. Name	SECTION I : IDENTIFICATION		
Present Past Other Name (if any): 2. Location	: Sukh Puri Swami ki Chhatri : :		
LONGITUDE 72 <sup>0</sup> 20 <sup>°</sup> E	LATITUDE 28 <sup>0</sup> 02 <sup>'</sup> N		
Address	Shamashanghat, Near-Gadisar Lake, Jaisalmer		
	: Village (village code) Post : Jaisalmer State : Rajasthan PIN: 345001		
Approach	<ul> <li>The Chhatri is situated at Shamshanghat. It is 1 k.m. away from Railway station Jaisalmer dist. It is well connected by regular bus service.</li> </ul>		

#### 3. Property Type

 Buildings	F	Religious structures		Other Structures
Palace	Τe	emple		Wall
Fort	Μ	osque		Gateway
Citadel	Μ	inar		Pillar
Govt. building	C	hurch		Others (specify)
Railway station	Μ	onastery		
Defence building	St	tupa		
Industrial building	Тс	omb, Mausoleum		
Other public buildings				
Residential building				
i toolaonnan banan g				
Engineering structure	Open	space and related	Not	e: This chhatri is made up on
Ŭ	-	space and related tures		te: This chhatri is made up on vated platform. The
Ŭ	<u>str</u> uc	•	elev	· · · · · · · · · · · · · · · · · · ·
Engineering structure	<i>struc</i> Pเ	tures	elev sup	vated platform. The
Engineering structure Bridge	struc Pi	<b>tures</b> ublic square	elev sup dov belo	vated platform. The perstructure had been fallen vn. Drum is decorated and pw it Lateral transept. It has
Engineering structure Bridge Tunnel	Struc Pi Pi G	<b>tures</b> ublic square ark or garden	elev sup dov belo folia	vated platform. The verstructure had been fallen vn. Drum is decorated and ow it Lateral transept. It has ated arch opening spandrel is
Engineering structure Bridge Tunnel	struc Pu Pa G	<b>tures</b> ublic square ark or garden raveyard	elev sup dov belo folia dec	vated platform. The verstructure had been fallen vn. Drum is decorated and ow it Lateral transept. It has ated arch opening spandrel is corated with medallion and
Engineering structure Bridge Tunnel	Struc Pi Pa Ba G Ba Ta	at <b>ures</b> ublic square ark or garden raveyard aolis, Well	elev sup dov belo folia dec	vated platform. The verstructure had been fallen vn. Drum is decorated and ow it Lateral transept. It has ated arch opening spandrel is

### 4. Property Use

	ABANDONED / IN USE : Abandoned
Present	:
Past	:
5. Age (Source)	
PERIOD	: 19 <sup>th</sup> Century AD
YEARS	:
Precise date of Construction	
Completion	
Subsequent changes	
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	•
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	: Memorial
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	
Archaeological	Eoliated arch

Archaeological Historical Religious Any other (specify)

Foliated arch

## **SECTION II: DESCRIPTION**

9.	Physical Description and De	cor	ative Features
•	Context Urban / Rural Setting Surroundings		* <b>Drawings</b> (Attach extra sheet if necessary) Urban
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 01
•	<b>Spatial Organization</b> Orientation Plan Allocation of Spaces	:	The Chhatri is oriented North/South and faces the South
•	<b>RCHITECTURAL STYLE</b> <b>Ornamentation</b> Exteriors Interiors Movable Collections <b>by Other</b> (specify)		Foliated arch, Medallion

#### **10. Construction Technology**

Structural System	:	Indo-Persian
Building Techniques	:	Trabeate system
Material of Construction	:	Stone, Plaster

#### 11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

#### In Brief (Attach extra sheet if necessary):

Dust and dirt deposition.

### 12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

# SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS