

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JSL-061

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Maharajadhiraj Champat Singh ki Bawari :	
LONGITUDE 72° 20' E	LATITUDE 28 ⁰ 02 ['] N	
LONGITUDE 72°20 E	LATITUDE 28° 02 N	
Address	Amar Sagar, Jaisalmer	
	: Village (village code) Amar Sagar Post : Amar Sagar District: Jaisalmer State : Rajasthan PIN: 345001	
Approach	The Bawari is situated at Amar Sagar in Jaisalmer. It is 5 k.m. away from Jaisalmer dist. It is well connected by regular car and jeep services.	

3. Property Type



4. Property Use

		ABANDONED / IN USE :	Abandoned
Present	:		
Past	:		
5. Age (Source)			
PERIOD		18 th Century AD	
YEARS	:	To Gentary AB	
Precise date of Construction	:		
Completion	:		
Subsequent changes	:		
Destruction / Demolition	:		
C. Ownership / Level of Protectic			
6. Ownership / Level of Protection SINGLE /MULTIPLE :			
		SINGLE /WIULTIFLE :	
	:		
India / State Archaeology			
Department / Any Other (Please			
specify) Private			
Any other (Please specify)	:		
Name	:		
Address			
Phone	:		
7. Association			
WITH EVENTS In History			
In Rituals	:		
In Building Construction	:		
Any other (specify)	÷		
WITH PERSONS	-		
Patron	:	Water reservoir	
Architect / Engineer	:		
Any other (specify)	:		
8. Statement of Significance			
Architectural			

Architectural Archaeological Historical Religious Any other (specify)

Pointed arch

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	: : :	(m / cm/ feet / inch)	
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Bawari is oriented North/South and faces the South	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Staircases, circular arch, pointed arch	

10. Construction Technology

Structural System	: Indo-Persian
Building Techniques	: Trabeate system
Material of Construction	: Stone and Plaster

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dust and dirt deposition, blackening of surface.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS