


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JSL-084

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any):	: Maharawal Sabal Singh ki Chhatri :	
2. Location		
LONGITUDE 72 ⁰ 20 ['] E	LATITUDE 28° 02' N	
Address	Bara Bag, Jaisalmer	
	: Village (village code) Post : Jaisalmer State : Rajasthan PIN: 345001	
Approach	: The Chhatri is situated at Bara Bag. It is 6 k.m. away from Jaisalmer dist. It is well connected by regular bus services.	

3. Property Type



4. Property Use

		ABANDONED / IN USE :	Abandoned
Present	:		
Past	:		
5. Age (Source)			
PERIOD	:	17 th Century AD	
YEARS	:		
Precise date of Construction	:		
Completion	:		
Subsequent changes	:		
Destruction / Demolition	:		
6. Ownership / Level of Protection	on		
· ·		SINGLE /MULTIPLE :	
Public : Archaeological Survey of	:		
India / State Archaeology			
Department / Any Other (Please			
specify)			
Private	:		
Any other (Please specify)	:		
Name	:		
Address	÷		
Phone	-		
7. Association			
WITH EVENTS			
In History	:		
In Rituals	:		
In Building Construction	:		
Any other (specify)	:		
WITH PERSONS			
Patron	:	Memorial	
Architect / Engineer	:		
Any other (specify)	÷		
8. Statement of Significance			

Architectural Archaeological Historical Religious Any other (specify)

Pedadeul superstructure

SECTION II: DESCRI

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01	
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The chhatri is oriented East/West and faces the East	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Pedadeul, amlak, Kangura pattern, pillars with capital	

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Trabeate system
Material of Construction	:	Stone and Plaster

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dust and dir deposition and Blackening of surface.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS