


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KRL-035

1. Name	SECTION I : IDENTIFICATION		
Present Past Other Name (if any):	: Nawal Bihari jee ka Mandir :		
2. Location			
LONGITUDE 77° 4' E	LATITUDE 27 ⁰ 3 ['] N		
Address	Chaube Para, Karauli		
	: Village (village code) Post : Karauli State : Rajasthan PIN: 322241		
Approach	: The Temple is situated at Karauli ciry. It is 2 k.m. away from Karauli bus stand. It is well connected by regular bus services.		
3. Property Type			
Buildings	Religious structures Other Structures		



4. Property Use

	ABANDONED / IN USE : In use			
Present Past	: Religious : Religious			
5. Age (Source)				
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	15 th Century A.D.			
6. Ownership / Level of Protection				
India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	SINGLE /MULTIPLE : Dev Sthan Vibhag Rajasthan			
 7. Association WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: Temple : :			
8. Statement of Significance				
Architectural	Foliated arch			

Archaeological Archaeological Historical Religious Any other (specify)

2

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented East-West and faces the East	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Foliated arch, fluted column, medallion	

10. Construction Technology

Structural System Building Techniques	:	Indo-Persian Arcuate system
Material of Construction	:	Stone and plaster

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface, plaster peeling off.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS