

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments Serial No.: RJ/KRL-061 **SECTION I: IDENTIFICATION** 1. Name Present Sitaram Mandir **Past** Other Name (if any): 2. Location LONGITUDE 77° 4' E 27⁰ 3' N LATITUDE Address Out of Nadi Darwaja, Karauli Village (village code) Post: Karauli District: Karauli State: Rajasthan PIN: 322241 **Approach** The Temple is situated at Karauli city. It is 3 km away from Karauli bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures **Other Structures** Palace Temple Wall Mosque Gateway Fort Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: The Temple is made on an structures elevated platform. It has foliated Bridge Public square arch entrance. The sanctum Park or garden santorum enshrines the painting of Tunnel Lord Sita Ram. Other engineering structure Graveyard Baolis. Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE: In Use
Present Past	: Religious : Religious
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: 19 th Century AD : :
6. Ownership / Level of Protecti	
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	SINGLE /MULTIPLE : : : : : : : : : : : : : : : : :
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: Temple : :
8. Statement of Significance	
Architectural Archaeological Historical Religious Any other (specify)	Foliated arch

SECTION II: DESCRIPTION

9.	Physical Description and De	ecora	ative Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / am/fact / inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation	:	The Temple is oriented North/South and faces the south.
	Plan Allocation of Spaces	:	South.
•	Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : :	Foliated arch
10	. Construction Technology		
11	Structural System Building Techniques Material of Construction Condition Assessment	: :	Indopersian Arcuate system Stone and plaster
1.1			
		ood	/ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance		
In	Brief (Attach extra sheet if r	nece	ssary):
۱۸/	all-maintained		

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
•	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS