


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KRL-155

1. Name	SECTION I : IDENTIFICATION
Present	: Pratap Pal ki Chhatri
Past Other Name (if any):	
Other Maine (ir ally).	•
2. Location	
LONGITUDE 77° 4' E	LATITUDE 27° 3' N
Address	Near Kasba Shahar Fort, Karauli
	: Village (village code) Post : Kasba Shahar District: Karauli State : Rajasthan PIN: 322204
Approach	: The Chhatri is situated at Kasba Shahar in Karauli district. It is 41 km. away from Karauli bus stand. It is well connected by regular bus services.

3. Property Type



4. Property Use

	ABANDONED / IN USE : Abandoned
Present Past	: Memorial : Memorial
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	17 th Century A.D.
	•
6. Ownership / Level of Protection	ION SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	
7. Association	
 WITH EVENTS In History In Rituals	Cenotaph : : :
8. Statement of Significance	
Architectural Archaeological Historical Religious	The structure has a large drum with ribbed pattern surmounted by pinnacle and inverted lotus.

Religious Any other (specify)

9. Physical Description and Decorative Features		
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) Urban	
Surroundings	Stand in Isolation Integral part of a Landscape / Street / Complex	
Quantification Area Dimension(L x B x	x H) : (m / cm/ feet / inch)	
Number of Blocks Number of Storys	: 01 : 01	
• Spatial Organization Orientation Plan Allocation of Spaces	The Chhatri is oriented East-West and faces the East	
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections Any Other (apagifu)	 Domical superstructure, spandrel decorated with fringe pattern. Medallion 	
Any Other (specify) 10. Construction Technolo	Pgy	
Structural System Building Techniques Material of Constructio	 Indo-Persian Arcuate system Sandstone & brick plaster 	
11. Condition Assessment		
In General	Good / Fair Good	
Sign of Deterioration		

Sign of Deterioration Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS