


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KRL-156

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	Abhay Chand Pal ki Chhatri
2. Location	
LONGITUDE 77° 4' E	LATITUDE 27° 3' N
Address	Near Kasba Shahar Fort, Karauli
	: Village (village code) Post : Kasba Shahar District: Karauli State : Rajasthan PIN: 322204
Approach	: The Chhatri is situated at Kasba Shahar in Karauli district. It is 41 km. away from Karauli bus stand. It is well connected by regular bus services.

3. Property Type



4. Property Use

	ABANDONED / IN USE : Abandoned	
Present Past	: Memorial : Memorial	
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	17 th Century A.D.	
6. Ownership / Level of Protection	on	
	SINGLE /MULTIPLE :	
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	:	
7. Association		
 WITH EVENTS In History In Rituals	: Cenotaph : : :	
8. Statement of Significance		
Architectural Archaeological Historical	The structure has a large domical superstructure with rib pattern surmounted by pinnacle and inverted lotus.	bed

Religious Any other (specify)

9. Physical Description and Decorative Features			
Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban	
		Stand in Isolation Integral part of a Landscape / Street / Complex	
• Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)	
Number of Blocks Number of Storys	:	01 01	
 Spatial Organization Orientation Plan Allocation of Spaces 	:	The Chhatri is oriented North-South and faces the South	
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	: : :	Domical superstructure with ribbed pattern. Lime murals	

10. Construction Technology

Structural System	: Indo-Persian
Building Techniques	: Arcuate system
Material of Construction	: Sandstone, Lime, etc.

11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS