



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KRL-208

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Sati Mata jee ka chhatri  
 Past :  
 Other Name (if any):

#### 2. Location

LONGITUDE 77° 4' E

LATITUDE 27° 3' N

#### Address

Bahadur Pur Fort, Karauli

: **Village (village code)**

**Post** : Bahadur Pur

**District**: Karauli

**State** : Rajasthan

**PIN**: 322218

#### Approach

: The chhatri is situated at Bahadur Pur in Karauli district. It is 20 km. away from Karauli. It is well connected by regular bus services.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)  
**chhatri**

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** The chhatri is dedicated to Sati Mata and is made on a highly elevated platform. It has domical superstructure and the well has Kangura pattern design. The entrance gate has screen work on both its both sides. The wall of the interior has alcoves and used as a temple

#### 4. Property Use

---

**ABANDONED / IN USE :** Abandoned

**Present** :  
**Past** :

#### 5. Age (Source)

---

**PERIOD** : 17<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of  
India / State Archaeology  
Department / Any Other (Please  
specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** : Cenotaph
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |   |
|-------------------------------------|---------------------|---|
| <input checked="" type="checkbox"/> | Architectural       | The chhatri is used as a religious place and has temple like feature from inside. |
| <input type="checkbox"/>            | Archaeological      |   |
| <input type="checkbox"/>            | Historical          |   |
| <input type="checkbox"/>            | Religious           |   |
| <input type="checkbox"/>            | Any other (specify) |   |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context** \* **Drawings** (Attach extra sheet if necessary)  
**Urban / Rural Setting** Rural setting  
**Surroundings** **Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
 Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
 Number of Blocks : 01  
 Number of Storys : 01
  
- **Spatial Organization**  
 Orientation : The chhatri is oriented north-south and faces the north  
 Plan :  
 Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
 Exteriors : Domical superstructure  
 Interiors : Alcoves  
 Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate system
- Material of Construction** : Bricks, sandstone

### 11. Condition Assessment

---

<b>In General</b>	<b>Good / Fair</b>
	Good

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

#### **In Brief (Attach extra sheet if necessary):**

Entrance portion is damaged. Needs proper maintenance.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input checked="" type="checkbox"/> | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**