



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KRL-297

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Shree Anand Bihari jee ka Mandir  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 77° 4' E

**LATITUDE** 27° 3' N

#### Address

Near-Gaushala Hindaun City, Karauli

: **Village (village code)**

**Post** : Hindaun City

**District:** Karauli

**State** : Rajasthan

**PIN:** 322230

#### Approach

: The Temple is situated at Hindaun city in Karauli district. It is 30 km. away from Karauli. It is well connected by regular bus services.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** The temple is dedicated to Lord Krishna. It has projected balcony supported by brackets. It has projected balcony supported by brackets. It has foliated arches opening supported by plasters & the spandrel is decorated with medallions. The interior has foliated arches decorated with fringe pattern & thick fluted columns. The walls have alcoves with oblong surface.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 17<sup>th</sup> Century AD  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** : Temple
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |   |
|-------------------------------------|---------------------|---|
| <input checked="" type="checkbox"/> | Architectural       | The temple has projected balcony as superstructure. |
| <input type="checkbox"/>            | Archaeological      |   |
| <input type="checkbox"/>            | Historical          |   |
| <input type="checkbox"/>            | Religious           |   |
| <input type="checkbox"/>            | Any other (specify) |   |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings**  
**\* Drawings** (Attach extra sheet if necessary)  
Urban  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) :  
(m / cm/ feet / inch)  
Number of Blocks : 01  
Number of Storys : 02
  
- **Spatial Organization**  
Orientation : The Temple is oriented East-West and faces the East  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Foliated arch, plaster medallion  
Interiors : Fluted columns, image of Lord Bauke Bihari  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate and Trabeate system
- Material of Construction** : Stone, brick and lime plaster

### 11. Condition Assessment

---

<b>In General</b>	<b>Good / Fair</b>
	Good

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

**In Brief** (Attach extra sheet if necessary):

Well maintained.

## 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

**NAME**

**NAME**

#### **18. Reviewers**

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**