

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KRL-325

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Shree Ambika Mata Mandir :
LONGITUDE 77 ⁰ 4 [°] E	LATITUDE 27° 3' N
Address	Dev Dwara Ward No-6, Toda Bhim, Karauli
	: Village (village code) Post : Toda Bhim District: Karauli State : Rajasthan PIN: 321611
Approach	: The Temple is situated at Toda Bhim in Karauli district. It is 72 km. away from Karauli. It is well connected by regular bus services.

3. Property Type

 Buildings		Religious structures		Other Structures
Palace	\checkmark	Temple		Wall
Fort		Mosque		Gateway
Citadel		Minar		Pillar
Govt. building		Church		Others (specify)
 Railway station		Monastery		
 Defence building		Stupa		
Industrial building		Tomb, Mausoleum		
Other public buildings				
Residential building				
Engineering structure	Open space and related structures			te: The temple is made on an vated platform. It has a circular
Bridge		Public square		h entrance. The wall of the
Tunnel		Park or garden	tem	ple also has alcoves. It has
Other engineering structure		Graveyard		belled arches supported by
		Baolis, Well		ngated columns. The structure
		Tank	has	
		Cave	suri	mounted by pinnacle.

4. Property Use ABANDONED / IN USE : In use Present Religious 2 Past : Religious 5. Age (Source) 16th Century AD PERIOD 2 YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private Prem Chand Yogi Pujari, Toda Bhim, Karauli 2 Any other (Please specify) : Name : Address 2 Phone ÷ 7. Association WITH EVENTS In History Temple 2 In Rituals In Building Construction 1 Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) 2 8. Statement of Significance Architectural The temple has corbelled arches \checkmark Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features		
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Rural Setting Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented North-South and faces the North
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections ny Other (specify)	: : :	Corbelled arch, circular arch Alcoves

10. Construction Technology

Structural System	: Indo – Persian
Building Techniques	: Arcuate system
Material of Construction	: Brick and stone

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface, peeling of plaster.

12. Threats to the Property

\checkmark	Natural
<	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS