

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KRL-343 **SECTION I: IDENTIFICATION** 1. Name Present Chaukh Darwaja Past Other Name (if any): 2. Location 270 3' N LONGITUDE 77° 4' E LATITUDE **Address** Batde, Karauli Village (village code) Batde Post: Langara District: Karauli State: Rajasthan **PIN:** 322249 Approach The Gateway is situated at Batde in Karauli district. It is 25 km. away from Karauli. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Temple Palace Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: The gateway is called as structures Chaukh Darwaja and is a big structure. It has pottika supported Public square Bridge by plasters. The mostly part of Tunnel Park or garden gateway is damaged. Graveyard Other engineering structure Baolis, Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present Past	: Gateway : Gateway
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protecti	: 16 th Century AD : : : : : : on
	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	: : : : :
7. Association	
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: Gateway : : :
8. Statement of Significance	
✓ Architectural	The structure has big plasters supporting the structure

SECTION II: DESCRIPTION

•	Context Urban / Rural Setting		* Drawings (Attach extra sheet if necessary) Rural Setting
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) :	(m / am/fact / inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch)
•	Spatial Organization Orientation	:	The Gateway is oriented North-South and faces the North
	Plan Allocation of Spaces	:	Notur
AR	CHITECTURAL STYLE		
•	Ornamentation		
	Exteriors Interiors	:	Plaster, pottika
	Movable Collections	•	
An	y Other (specify)	:	
10.	. Construction Technology		
	Structural System	:	Indo – Persian
	Building Techniques	:	Arcuate and trabeate system
	Material of Construction	:	Brick and stone
11.	. Condition Assessment		
		Good Fair	/ Fair
√	Sign of Deterioration Serious Deterioration Danger of Disappearance		
In	Brief (Attach extra sheet if	nacas	scaru).

In Brief (Attach extra sheet if necessary):

Almost complete gateway is damaged, needs restoration.

12. Threats to the Property

✓	Natural
✓	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS