

## Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/KTP-30

<u>SI</u> 1. Name	ECTION I : IDENTIFICATION
Present Past Other Name (if any):	: Kachahri Wali Haveli :
2. Location	
LONGITUDE 76° 16' E	LATITUDE 27 <sup>0</sup> N
Address	Ward No-20, Buchahera
Approach	<ul> <li>Village (village code) Post : Kotputli District: Jaipur State : Rajasthan PIN: 303108</li> <li>The Haweli is situated 1 km. East of NH-8 near Bus Stand.</li> </ul>
3. Property Type	
Buildings         Palace         Fort         Citadel         Govt. building         Railway station         Defence building         Industrial building         Other public buildings         ✓	Religious structuresOther StructuresTempleWallMosqueGatewayMinarPillarChurchOthers (specify)MonasteryStupaTomb, Mausoleum
Engineering structure         Bridge         Tunnel         Other engineering structure	Open space and related structuresNote: It was a grand haweli which is now in dilapidated state. It is made of Bricks and Stone.Public square Park or garden Graveyard Baolis, Well Tank CaveNote: It was a grand haweli which is now in dilapidated state. It is made of Bricks and Stone.

esidence (some portion is in use rest abandoned esidence cum Cachahri
esidence cum Cachahri
SINGLE /MULTIPLE :

# 

# **SECTION II: DESCRIPTION**

cor	ative Features
	<ul> <li>* Drawings (Attach extra sheet if necessary)</li> <li>Rural setting surroundings.</li> <li>Stand in Isolation</li> <li>Integral part of a Landscape / Street / Complex</li> </ul>
::	(m / cm/ feet / inch) 03 02 The building is oriented North-South And faces the South.
:	Jharokhas and windows. Cloistered verandah and room.

### **10. Construction Technology**

Structural System	:	Indo-Persian
<b>Building Techniques</b>	:	Arcuate System
Material of Construction	:	Lakhori Brick, Stone and Lime mortar.

#### **11. Condition Assessment**

In General

Good / Fair

1		
	$\checkmark$	

Sign of Deterioration Serious Deterioration Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

Dilapidated.

## 12. Threats to the Property

<	Nati
	Neg
	Van
$\checkmark$	Urb

Natural Negligence Vandalism Urban Pressures

# **SECTION III:** REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS