

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KTP-79 **SECTION I: IDENTIFICATION** 1. Name Present Dada Bhawan Past Other Name (if any): 2. Location LONGITUDE 76° 16' E 27⁰ 43['] N LATITUDE **Address** Village (village code) Sunderpura District: Jaipur Post: Kotputli State: Rajasthan PIN: 303108 Approach The building situated 6 k.m. away from Kotputli Bus Stand in the village named Sunderpura. 3. Property Type **Buildings** Religious structures **Other Structures** Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is an impressive haveli structures with decorated façade having three multi-foliated arches. It is a Public square Bridge double storey structure. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use		
		ABANDONED / IN USE :
Present		Residence
Past	:	Residence
5. Age (Source)		
PERIOD YEARS	•	19 th Century A.D.
Precise date of Construction	:	19 Century A.D.
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
o. Ownership? Level of 1 Totecti	<u> </u>	SINGLE /MULTIPLE :
		SINGLE /MIDLTIFLE .
	:	
India / State Archaeology		
Department / Any Other (Please specify)		
Private		
Any other (Please specify)	:	
Name	:	Jaidayal
Address	:	Sundarpura, Kotputli
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
 WITH PERSONS 		
Patron	:	
Architect / Engineer	:	
Any other (specify)	•	
8. Statement of Significance		
✓ Architectural	Tr	adition Rajasthani Haveli
Archaeological	116	aution rajastitani Haveii
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9.	Physical Description and D	ecora	ative Features
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)) :	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	02 02
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The building oriented East-West and faces East.
<u>AF</u>	CHITECTURAL STYLE Ornamentation Exteriors Interiors	:	Foliated arch opening
An	Movable Collections y Other (specify)	:	The interior is in bad shape due to negligence
10	. Construction Technology		
	Structural System Building Techniques Material of Construction	:	Indo-Persian Arcuate system Brick, stone and plaster.
11	. Condition Assessment		
	In General	Good	/ Fair
√	Sign of Deterioration Serious Deterioration Danger of Disappearance		
In	Brief (Attach extra sheet if	neces	ssary):

Interior is in a state of dilapidation due to negligence.

12. Threats to the Property		
	✓	Natural
	✓	Negligence
		Vandalism
		Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS