

1. Name

Present

2. Location

Address

Approach

3. Property Type

Palace

Citadel

Bridge

Tunnel

Govt. building

Railway station

Defence building

Industrial building
Other public buildings
Residential building

Engineering structure

Other engineering structure

Fort

Buildings

Other Name (if any):

LONGITUDE 76° 16' E

Past

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KTP-108 **SECTION I: IDENTIFICATION Babul Gujar House** 27⁰ 43['] N LATITUDE Village (village code) Mulahera Post: Kotputli District: Jaipur State: Rajasthan PIN: 303108 The building situated in Mulahera village which is 4 km away from Kotputli Bus Stand Religious structures Other Structures Temple Wall Mosque Gateway Minar Pillar Others (specify) Church Monastery Stupa Tomb, Mausoleum Note: The old haveli is in ruins. Open space and related structures

Public square Park or garden

Graveyard Baolis, Well Tank Cave

4. Property Use			
		ABANDONED / IN USE :	
Present	:	Residence	
Past	:	Residence	
5. Age (Source)			
PERIOD	:		
YEARS	:	19 th Century A.D.	
Precise date of Construction	:	•	
Completion	:		
Subsequent changes	:		
Destruction / Demolition	:		
6. Ownership / Level of Protection	on		
		SINGLE /MULTIPLE :	
India / State Archaeology Department / Any Other (Please specify) Private	:		
Any other (Please specify) Name	:	Hari Dom Cuiar	
Address	•	Hari Ram Gujar	
Phone	:		
7. Association			
WITH EVENTS			
In History	:		
In Rituals	:		
In Building Construction	:		
Any other (specify)	:		
 WITH PERSONS 			
Patron	:		
Architect / Engineer	:		
Any other (specify)	:		
8. Statement of Significance			
Architectural			
Archaeological			
Historical			
Religious			
Any other (specify)			

SECTION II: DESCRIPTION

9.	Physical Description and De	cor	ative Features
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Rural Setting
	Curroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 02
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Building oriented east – west and faces the east.
•	Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : :	Core materials are exposed
10	. Construction Technology		
	Structural System Building Techniques Material of Construction	: : :	English-Bond-Method Lakhori bricks, wood and lime plaster
11. Condition Assessment			
	In General G	ood	/ Fair
✓ ✓	Sign of Deterioration Serious Deterioration Danger of Disappearance		
	Brief (Attach extra sheet if n	ece	ssary):
Dil	apidated		

12.	Threats	to the	Pro	perty
------------	----------------	--------	-----	-------

✓	Natural
✓	Negligence
✓	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
6 7.11 1.16.11	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS