

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KTP-110

1. Name	SECTION I: IDENTIFICATION	1		
Present Past Other Name (if any):	: Ram Mandir : :			
2. Location				
LONGITUDE 76° 16' E	LATITUDE 27 ⁰ 43 ['] N			
Address				
	: Village (village code) Post : Kotputli State : Rajasthan	Mulahera District: Jaipur PIN: 303108		
Approach	: The Temple situated in Mulahera village which is 4 km away from Kotputli Bus Stand			
3. Property Type				
Buildings	<i>Religious structures</i> ✓ Temple	Other Structures		
Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Gateway Pillar Others (specify)		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic square Park or gardenGraveyard Baolis, Well Tank Cave	Note: This temple is in dilapidated state. It is made of Lakhori bricks and has been plastered with lime. It is a double storey structure. A large part of it has fallen down.		

4. Property Use ABANDONED / IN USE : Present Religious : Past : Religious 5. Age (Source) PERIOD 20th Century A.D. YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : **Gujar Community** India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address : Phone ÷ 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Double storey structure Archaeological Historical

Religious

Any other (specify)

SECTION II: DESCRIPTION

•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Rural Setting	
			Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:		
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch 01 02	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple oriented North-South and faces the North.	
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)		Dilapidated façade Locked	

10. Construction Technology

Structural System	:	
Building Techniques	:	English-Bond Method
Material of Construction	:	Lakhori bricks and lime plaster

11. Condition Assessment

In General

Good / Fair

✓

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dilapidated

12. Threats to the Property

✓ Natural
 ✓ Negligence
 ✓ Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS