

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KTP-116

1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Chamaro ka Kuan (Well) : :	
LONGITUDE 76° 16' E Address	LATITUDE 27 ^o 43 ['] N	
Approach 3. Property Type	 Village (village code) Post: Kotputli State: Rajasthan The Well situated in the is 4 k.m. away from Kotp 	Mulahera District: Jaipur PIN: 303108 village named Mulahera which outli Bus stand.
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	•	Note: It is an old well. It has been encased with dressed masonry.

4. Property Use	
	ABANDONED / IN USE :
Present Past	: Dried up: Drinking (for villagers)
5. Age (Source)	
PERIOD YEARS Precise date of Construction	: : 18 th Century A.D.
Completion Subsequent changes Destruction / Demolition	: : :
6. Ownership / Level of Protection	ion
	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private	:
Any other (Please specify)	:
Name Address	: :
Phone	· :
7. Association	
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify)	: : : :
8. Statement of Significance	
 ✓ Architectural Archaeological Historical Religious Any other (specify) 	Irrigation & Drinking water

SECTION II: DESCRIPTION

9.	Physical Description and De	ecor	ative reatures
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Rural Setting
	ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	(mi / cm/ leet / inch)
•	Spatial Organization Orientation Plan Allocation of Spaces	: :	The well oriented east-west and faces west.
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : : : : : : : : : : : : : : : : : :	Plastered rim around the circular well. Innerface is plastered.
10.	Construction Technology		
	Structural System Building Techniques Material of Construction	: :	Circular well Dressed Stone and plaster
11.	Condition Assessment		
	In General G	ood	l / Fair
√ 	Sign of Deterioration Serious Deterioration Danger of Disappearance		occaru).
	Brief (Attach extra sheet if r	iece	:55ai y j.
٧e	getational growth.		

12. Threats to the Property		
	✓	Natural
	✓	Negligence
		Vandalism
		Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS