



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/NGR-014

SECTION I : IDENTIFICATION

1. Name

Present : Nahar Pole
 Past :
 Other Name (if any): :

2. Location

LONGITUDE 75° 15' E

LATITUDE 27° 40' N

Address	Nahar pole, Gandhi Chowk, Nagaur		
	:	Village (village code)	Nagaur city
		Post: Nagaur City	District: Nagaur
		State: Rajasthan	PIN: 341001

Approach : The Gateway is situated at Nagaur. It is 1km away from bus stand, Nagaur. It is well connected by regular bus services.

3. Property Type

Buildings

<input type="checkbox"/>	Palace
<input type="checkbox"/>	Fort
<input type="checkbox"/>	Citadel
<input type="checkbox"/>	Govt. building
<input type="checkbox"/>	Railway station
<input type="checkbox"/>	Defence building
<input type="checkbox"/>	Industrial building
<input type="checkbox"/>	Other public buildings
<input type="checkbox"/>	Residential building

Religious structures

<input type="checkbox"/>	Temple
<input type="checkbox"/>	Mosque
<input type="checkbox"/>	Minar
<input type="checkbox"/>	Church
<input type="checkbox"/>	Monastery
<input type="checkbox"/>	Stupa
<input type="checkbox"/>	Tomb, Mausoleum

Other Structures

<input type="checkbox"/>	Wall
<input checked="" type="checkbox"/>	Gateway
<input type="checkbox"/>	Pillar
<input type="checkbox"/>	Others (specify)-

Engineering structure

<input type="checkbox"/>	Bridge
<input type="checkbox"/>	Tunnel
<input type="checkbox"/>	Other engineering structure

Open space and related structures

<input type="checkbox"/>	Public square
<input type="checkbox"/>	Park or garden
<input type="checkbox"/>	Graveyard
<input type="checkbox"/>	Baolis, Well
<input type="checkbox"/>	Tank
<input type="checkbox"/>	Cave

Note: It is one of the Gateway of the old fort Nagaur. It has pointed arch opening. There is medallion on the spandrel. It is built of stone rubble masonry. On both the sides the gateway has been encroached by shops.

4. Property Use

ABANDONED / IN USE : In use

Present : Gateway
Past : Gateway

5. Age (Source)

PERIOD : 12th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of
India / State Archaeology
Department / Any Other (Please
specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban✓ / Rural Setting
Surroundings

*** Drawings** (Attach extra sheet if necessary)
Urban setting

Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**

Area Dimension (L x B x H) :

(m / cm/ feet / inch)

Number of Blocks : 01
Number of Storys : 01

- **Spatial Organization**

Orientation : The Gateway is oriented East/West and faces the East.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**

Exteriors : Medallion on the sprendel.

Interiors :

Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System : Indo-Persian.
Building Techniques : Arcuate techniques.
Material of Construction : Red sand stone.

11. Condition Assessment

In General

Good ✓ / Fair

- | | |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Discoloration, accumulation of dust and dirt.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input checked="" type="checkbox"/> | Negligence |
| <input checked="" type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

Gupta Dr.Mohan Lal, Udaipur Sambhag Ka Jilevar Sanskritik aur eatihasik adhayayan, Rajasthani Granthagar,Jodhpur, 2007-2009

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS

