



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/NGR-029

SECTION I: IDENTIFICATION

1. Name

Present : Hadi Rani Palace
Past :
Other Name (if any):

2. Location /

LONGITUDE 75°15'E

LATITUDE 27°40'N

Address

Hadi Rani palace, Nagaur Fort.

: Village (village code)

Post: Nagaur city

District: Nagaur

State: Rajasthan

PIN: 341001

Approach

: The Palace is situated near Nagaur Fort in Nagaur District. It is 2km away from bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|-------------------------------------|------------------------|
| <input checked="" type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: It is a multistoried masonic structure having foliated arch opening. Arch has medallion on the spandrel. Projected chhajjas are supported by stone brackets. The structure is adorned with perforated windows. The internal

walls and ceiling are embellished

4. Property Use

ABANDONED √/ IN USE

:

Present :palace

Past :palace

5. Age (Source)

PERIOD : 17th Century AD

YEARS :

Precise date of Construction :

Completion :

Subsequent changes :

Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of
India / State Archaeology
Department / Any Other (Please
specify)

Private :

Any other (Please specify) :

Name :

Address :

Phone :

7. Association

- **WITH EVENTS**

In History :

In Rituals :

In Building Construction :

Any other (specify) :

- **WITH PERSONS**

Patron :

Architect / Engineer :

Any other (specify) :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	. Arch has medallion on the spandrel.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban✓ / **Rural Setting**
Surroundings

* **Drawings** (Attach extra sheet if necessary)

Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**

Area Dimension (L x B x H) :

(m / cm/ feet / inch)

Number of Blocks : 02
Number of Storys : 02

- **Spatial Organization**

Orientation : The palace is oriented North/South and faces the South.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**

Exteriors : Foliated arch opening projected chhajjas supported by stone brackets.

Interiors :

Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System : Indo-Islamic
Building Techniques : Arcuate system
Material of Construction : Stone and plaster.

11. Condition Assessment

In General

Good / ☒ Fair

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

. Pilling of plaster, blackening of the surface deposition of sooth, discoloration etc.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS