



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/NGR-076

SECTION I : IDENTIFICATION

1. Name

Present : Narsingh Mandir
 Past :
 Other Name (if any):

2. Location

LONGITUDE 75° 15' E

LATITUDE 27° 40' N

Address	Near Jhara Talab, Nagaur		
	:	Village (village code)	Nagaur city
		Post : Nagaur City	District: Nagaur
		State : Rajasthan	PIN: 341001

Approach : The Temple is situated near Jhara Talab, in Nagaur. It is 3km away from bus stand, Nagaur. It is well connected by regular bus services.

3. Property Type

Buildings

<input type="checkbox"/>	Palace
<input type="checkbox"/>	Fort
<input type="checkbox"/>	Citadel
<input type="checkbox"/>	Govt. building
<input type="checkbox"/>	Railway station
<input type="checkbox"/>	Defence building
<input type="checkbox"/>	Industrial building
<input type="checkbox"/>	Other public buildings
<input type="checkbox"/>	Residential building

Religious structures

<input checked="" type="checkbox"/>	Temple
<input type="checkbox"/>	Mosque
<input type="checkbox"/>	Minar
<input type="checkbox"/>	Church
<input type="checkbox"/>	Monastery
<input type="checkbox"/>	Stupa
<input type="checkbox"/>	Tomb, Mausoleum

Other Structures

<input type="checkbox"/>	Wall
<input type="checkbox"/>	Gateway
<input type="checkbox"/>	Pillar
<input type="checkbox"/>	Others (specify)-

Engineering structure

<input type="checkbox"/>	Bridge
<input type="checkbox"/>	Tunnel
<input type="checkbox"/>	Other engineering structure

Open space and related structures

<input type="checkbox"/>	Public square
<input type="checkbox"/>	Park or garden
<input type="checkbox"/>	Graveyard
<input type="checkbox"/>	Baolis, Well
<input type="checkbox"/>	Tank
<input type="checkbox"/>	Cave

Note: The Temple has a open courtyard and stands on a raised platform. It has foliated arches, floral motif on the spandrel above it. Entrance has all the decorative features like floral motif, ala, creeper design etc. Arches are foliated. The temple has large portico and verandah. It is with

Shivlingam and Ram Janaki
Sculptor. The upper floor has

4. Property Use

ABANDONED / IN USE : Abandoned

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 17th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of
India / State Archaeology
Department / Any Other (Please
specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|-------------------------------------|------------------------------|
| <input checked="" type="checkbox"/> | Architectural- Foliated arch |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban✓ / Rural Setting
Surroundings
*** Drawings** (Attach extra sheet if necessary)
Urban setting
Stand in Isolation
Integral part of a Landscape / Street / Complex
- **Quantification**
Area Dimension (L x B x H) :

(m / cm/ feet / inch)

Number of Blocks : 01
Number of Storys : 01
- **Spatial Organization**
Orientation : The Temple is oriented East/West and faces the West.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Spandrel has the floral motif.
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** :
- Building Techniques** : Arcuate system.
- Material of Construction** : Stone, plaster, surkhi.

11. Condition Assessment

In General

Good / ✓Fair

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Peeling plaster expose the core material, vegetational growth.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input checked="" type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS

