

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological and Heritage Sites / Monuments**

Serial No.: RJ/NGR-104 **SECTION I: IDENTIFICATION** 1. Name Present Shaitan Singh Ka Well **Past** Other Name (if any): 2. Location / LONGITUDE 75°15'E **LATITUDE** 27°40'N Address Near, Mundiyar Talab. Village (village code) Post: Mundiyar **District**: Nagaur State: Rajasthan **PIN: 341028** Approach The Well is situated near Mundiyar Talab at Mundiyar in Nagaur District. It is 25km away from Nagaur. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a circular well cladded structures with rubble masonry and limeplaster. The well is not in use. Public square Bridge Tunnel Park or garden Other engineering structure Gravevard Baolis, Well Tank Cave

4. Property Use

**ABANDONED ∜** IN USE

:

Present : Well Past : Well

5. Age (Source)

PERIOD : 17<sup>th</sup> Century AD

YEARS

Precise date of Construction :

Completion :

Subsequent changes : Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE:

**Public**: Archaeological Survey of :

India / State Archaeology

Department / Any Other (Please

specify)

Private :

Any other (Please specify)

Name : Address :

Phone :

7. Association

• WITH EVENTS

In History

In Rituals :

In Building Construction

Any other (specify) :

• WITH PERSONS

Patron :

Architect / Engineer : Any other (specify) :

8. Statement of Significance					
V	Architectural Archaeological Historical		. Circular Well		
	Religious Any other (specify)	:			
SECTION II: DESCRIPTION					
9.	Physical Description and De	cora	ative Features		
•	Context Urban / Rural Setting Surroundings		* <b>Drawings</b> (Attach extra sheet if necessary)		
	Carrounanigo		Stand in Isolation Integral part of a Landscape / Street / Complex		
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)		
	Number of Blocks Number of Storys	:	(III / CIII/ leet / lilcii)		
•	Spatial Organization Orientation Plan Allocation of Spaces	: : : :	The Well is oriented North/South and faces the South.		
<u>AF</u>	CHITECTURAL STYLE Ornamentation Exteriors Interiors	:			
	Movable Collections  ny Other (specify)  Construction Technology	:			
	. Construction Technology				
Structural System Building Techniques Material of Construction		:	Well cladded with rubble masonry and lime-plaster.		
	:	Rubble masonry			

11. Condition Assessment					
In General	Good√ / Fair				
	Sign of Deterioration Serious Deterioration Danger of Disappearance				
In Brief (Attach extra sheet	if necessary):				
Pilling of plaster, cracks, badly damaged.					
12. Threats to the Property					
	√ Natural				
	Negligence				
	Vandalism Urban Pressures				
	015411110554105				

## **SECTION III:** REFERENCES

## 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS