

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No: RJ/NGR-109 **SECTION I: IDENTIFICATION** 1. Name Present Shiv Mandir **Past** Other Name (if any): 2. Location **LONGITUDE** 75°15'E LATITUDE 27°40'N Address Mundiyar Talab, Mundiyar Village (village code) Post: Mundiyar **District**: Nagaur State: Rajasthan **PIN**: 3141028 Approach district The Temple is situated near Mundiyar Talab at Mundiyar in Nagaur district. It is 25km away from Nagaur bus stand. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Wall Palace Temple Fort Mosque Gateway Minar Citadel Pillar Govt. building Church Others (specify) Railway station Monastery Khandhar Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related **Note:** It is an old temple in ruined structures condition. The area is scattered Public square with debris and garbage remains Bridge the temple architectural past can Tunnel Park or garden be seen all over the area .The ruin Other engineering structure Graveyard has Nandi and Lingam. Baolis, Well Tank Cave

4. Property Use				
		ABANDONED√ / IN USE		
Present	:			
Past	:	Religious		
5. Age (Source)				
PERIOD		17 <sup>th</sup> Century AD		
YEARS	:	17 Century AD		
Precise date of Construction	:			
Completion Subsequent changes	:			
Destruction / Demolition	:			
6. Ownership / Level of Protection	on			
		SINGLE /MULTIPLE :		
Public: Archaeological Survey of	:			
India / State Archaeology Department / Any Other (Please				
specify)state Govt.				
Private	:			
Any other (Please specify)	:			
Name	:			
Address Phone	:			
riione	•			
7. Association				
WITH EVENTS				
In History	:			
In Rituals	:			
In Building Construction	:			
Any other (specify)  • WITH PERSONS	•			
Patron				
Architect / Engineer	:			
Any other (specify)	:			
-				
8. Statement of Significance				
√ Architectural	Nic	thes on the wall		
Archaeological				
Historical				

Religious Any other (specify)	:		
SECTION II: DESCRIPTION			
<ul> <li>9. Physical Description and De</li> <li>Context         Urban √/ Rural Setting         Surroundings</li> </ul>	* Drawings (Attach extra sheet if necessary)  Stand in Isolation Integral part of a Landscape / Street / Complex		
Quantification     Area Dimension ( L x B x H)  Number of Blocks Number of Storys	: (m / cm/ feet / inch) :		
<ul> <li>Spatial Organization         Orientation         Plan         Allocation of Spaces     </li> </ul>	<ul><li>The Temple is oriented East/West and faces the East.</li><li>:</li></ul>		
• Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	: : :		
10. Construction Technology  Structural System Building Techniques Material of Construction	: : Stone		

11. Condition Assessn	nent
In General	Good / √Fair
	Sign of Deterioration  √ Serious Deterioration  Danger of Disappearance
In Brief (Attach extra s	heet if necessary):
The area has scattered	remains of the temple all over.
12. Threats to the Prop	perty
	Natural  √ Negligence  Vandalism  Urban Pressures

## **SECTION III:** REFERENCES

## 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS