



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/NGR-215

### SECTION I: IDENTIFICATION

#### 1. Name

Present : Mandir  
Past :  
Other Name (if any): :

#### 2. Location

LONGITUDE 75°15'E

LATITUDE 27°40'N

#### Address

Dilwara road Chenar

: **Village (village code)** Chenar

**Post:** Nagaur

**District:** Nagaur

**State:** Rajasthan

**PIN:** 341001

#### Approach

: The Temple is situated on Dilwara road at Chenar in Nagaur District. It is 1km away from bus stand, Nagaur. It is well connected by regular bus services.

#### 3. Property Type

##### **Buildings**

- ☐ Palace
- ☐ Fort
- ☐ Citadel
- ☐ Govt. building
- ☐ Railway station
- ☐ Defence building
- ☐ Industrial building
- ☐ Other public buildings
- ☐ Residential building

##### **Religious structures**

- ☒ Temple
- ☐ Mosque
- ☐ Minar
- ☐ Church
- ☐ Monastery
- ☐ Stupa
- ☐ Tomb, Mausoleum

##### **Other Structures**

- ☐ Wall
- ☐ Gateway
- ☐ Pillar
- ☐ Others (specify)-

##### **Engineering structure**

- ☐ Bridge
- ☐ Tunnel
- ☐ Other engineering structure

##### **Open space and related structures**

- ☐ Public square
- ☐ Park or garden
- ☐ Graveyard
- ☐ Baolis, Well
- ☐ Tank
- ☐ Cave

**Note:** It is a small but very old temple erected on mound. Square in shape and travesty technique is used for constructing the temple. Temple have dome with bijpurak Kalash.

---

**4. Property Use****ABANDONED / IN USE :** Abandoned

**Present** : Religious  
**Past** : Religious

---

**5. Age (Source)**

**PERIOD** : 18<sup>th</sup> Century AD  
**YEARS** :

**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

---

**6. Ownership / Level of Protection****SINGLE / MULTIPLE :**

**Public** : Archaeological Survey of  
India / State Archaeology  
Department / Any Other (Please  
specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

---

**7. Association****• WITH EVENTS**

**In History** : As per local myths and people it is the place where a  
saint lives and he was so powerful in spirituality that  
The maharajas of that time come to receive  
“Aashirwad” for his victory and he own.

**In Rituals** : √  
**In Building Construction** :  
**Any other (specify)** :

**• WITH PERSONS**

**Patron** :  
**Architect / Engineer** :  
**Any other (specify)** :

---

**8. Statement of Significance**

- |                                     |                                 |
|-------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> | Architectural- Square in shape. |
| <input type="checkbox"/>            | Archaeological                  |
| <input type="checkbox"/>            | Historical                      |
| <input type="checkbox"/>            | Religious                       |
| <input type="checkbox"/>            | Any other (specify)             |

:

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context**  
**Urban√ / Rural Setting**  
**Surroundings**  

**\* Drawings** (Attach extra sheet if necessary)  
Urban setting  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
- **Quantification**  
Area Dimension ( L x B x H ) :  

(m / cm/ feet / inch)

  
Number of Blocks : 01  
Number of Storys : 01
- **Spatial Organization**  
Orientation : The Temple is oriented East/West and faces the East.  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors :  
Interiors : Celestial deity installed in rised platform.  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

- Structural System** :
- Building Techniques** : Trabeate system.
- Material of Construction** : Random rubble stone and plaster.

## 11. Condition Assessment

---

**In General**

**Good / Fair**

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Sign of Deterioration  
Serious Deterioration  
Danger of Disappearance

**In Brief (Attach extra sheet if necessary):**

Due to latter renovation work the features and the originality disappear, it needs maintenance.

## 12. Threats to the Property

---

<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Natural  
Negligence  
Vandalism  
Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(Attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

(Related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**