



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/NGR-220

### SECTION I: IDENTIFICATION

#### 1. Name

Present : Gateway  
Past :  
Other Name (if any):

#### 2. Location

LONGITUDE 75°15'E

LATITUDE 27°40'N

#### Address

Lakholawa Talon ka Pul, Mundwa

: **Village (village code)** Mundwa

**Post:** Mundwa

**District:** Nagaur

**State:** Rajasthan

**PIN:** 341026

#### Approach

: The Temple is situated near Lakholawo Talab at Mundwa in Nagaur District. It is 18km away from bus stand, Nagaur. It is well connected by regular bus services..

#### 3. Property Type

##### *Buildings*

- ☐ Palace
- ☐ Fort
- ☐ Citadel
- ☐ Govt. building
- ☐ Railway station
- ☐ Defence building
- ☐ Industrial building
- ☐ Other public buildings
- ☐ Residential building

##### *Religious structures*

- ☐ Temple
- ☐ Mosque
- ☐ Minar
- ☐ Church
- ☐ Monastery
- ☐ Stupa
- ☐ Tomb, Mausoleum

##### *Other Structures*

- ☐ Wall
- ☒ Gateway
- ☐ Pillar
- ☐ Others (specify)-

##### *Engineering structure*

- ☐ Bridge
- ☐ Tunnel
- ☐ Other engineering structure

##### *Open space and related structures*

- ☐ Public square
- ☐ Park or garden
- ☐ Graveyard
- ☐ Baolis, Well
- ☐ Tank
- ☐ Cave

**Note:** The Facade have semi-circular arch with creeper designs. Alcoves on both sides of the Gateway make an impressive look.

---

**4. Property Use****ABANDONED / IN USE :** In use

**Present** : Gateway  
**Past** : Gateway

---

**5. Age (Source)**

**PERIOD** : 15<sup>th</sup> Century AD  
**YEARS** :

**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

---

**6. Ownership / Level of Protection****SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of  
India / State Archaeology  
Department / Any Other (Please  
specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

---

**7. Association**

- **WITH EVENTS**
  - In History** :
  - In Rituals** : ✓
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

---

**8. Statement of Significance**

- |                                     |                                      |
|-------------------------------------|--------------------------------------|
| <input checked="" type="checkbox"/> | Architectural- semi circular arches. |
| <input type="checkbox"/>            | Archaeological                       |
| <input type="checkbox"/>            | Historical                           |
| <input type="checkbox"/>            | Religious                            |
| <input type="checkbox"/>            | Any other (specify)                  |

:

## **SECTION II: DESCRIPTION**

### **9. Physical Description and Decorative Features**

---

- **Context**  
**Urban√ / Rural Setting**  
**Surroundings**  
**\* Drawings** (Attach extra sheet if necessary)  
Urban setting  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
- **Quantification**  
Area Dimension ( L x B x H) :  

(m / cm/ feet / inch)

  
Number of Blocks : 01  
Number of Storys : 01
- **Spatial Organization**  
Orientation : The Gateway is oriented North/South and faces the North.  
Plan :  
Allocation of Spaces :

### **ARCHITECTURAL STYLE**

- **Ornamentation**  
Exteriors : Semi-circular arches with different floral motifs.  
Interiors : Floral motifs.  
Movable Collections :  
**Any Other** (specify) :

### **10. Construction Technology**

---

<b>Structural System</b>	Indo-Persian.
<b>Building Techniques</b>	Arcuate system.
<b>Material of Construction</b>	Dressed stone and lime plaster.

## 11. Condition Assessment

---

In General

Good<sup>√</sup> / Fair

- |                                     |                         |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/>            | Serious Deterioration   |
| <input type="checkbox"/>            | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

---

## 12. Threats to the Property

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input checked="" type="checkbox"/> | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**