



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/NGR-280

SECTION I : IDENTIFICATION

1. Name

Present : Hanuman Mandir
Past :
Other Name (if any): :

2. Location

LONGITUDE 75° 15' E

LATITUDE 27° 40' N

Address

Near Amba Bawari, Merta city.

: **Village (village code)**

Post: Merta City

District: Nagaur

State: Rajasthan

PIN: 341510

Approach

: The Mandir is situated near Amba Bawari. It is 80km. from Bus stand, Nagaur. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |

Note: The temple is an old structure made of stone. The main complex has a façade which has pillars supporting the chajja. The complex has an egg(anda) shape dome which has an inverted lotus

<input type="checkbox"/>	Tank
<input type="checkbox"/>	Cave

and an amalsar, the stupika is present

4. Property Use

ABANDONED / IN USE

√ :

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 17th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

☒ Architectural

Façade supported by pillars

<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

- **Context** *** Drawings** (Attach extra sheet if necessary)
Urban / Rural Setting Urban Setting
Surroundings **Stand in Isolation**
Integral part of a Landscape / Street / Complex

- **Quantification**
 Area Dimension (L x B x H) : (m / cm/ feet / inch)

 Number of Blocks : 01
 Number of Storys : 01

- **Spatial Organization**
 Orientation : The Mandir is oriented East/West and faces the West.
 Plan :
 Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
 Exteriors : A new complex is being built within the complex
 Interiors :
 Movable Collections :
Any Other (specify) :

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Door is based on Arcuate Pattern with floral motifs
Material of Construction	:	stone

11. Condition Assessment

In General	Good / Fair
-------------------	--------------------

<input type="checkbox"/>	Sign of Deterioration
<input type="checkbox"/>	Serious Deterioration

☐ Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Degradation

12. Threats to the Property

√	Natural
	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

Not available

14. Photographs

(Attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(Related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS