

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/NGR-286 **SECTION I: IDENTIFICATION** 1. Name Present Gateway **Past** Other Name (if any): Fort Ka Gate 2. Location / LONGITUDE 75°15'E **LATITUDE** 27°40'N Address Malkot Fort Merta city Village (village code) **Post:** Merta City **District**: Nagaur **PIN:** 341510 State: Rajasthan Approach The Gate is situated near Malkot Fort in Merta city in Nagaur District. It is 80km away from Nagaur. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: The Gateway is in ruined structures state. It has pointed arch opening. The Gateway has closed. Public square Bridge Tunnel Park or garden Other engineering structure Gravevard Baolis, Well Tank Cave

4. Property Use

ABANDONED ∜ IN USE

:

Present : Gateway
Past : Gateway

5. Age (Source)

PERIOD : 17th Century AD

YEARS

Precise date of Construction :

Completion :

Subsequent changes : Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE:

Public: Archaeological Survey of :

India / State Archaeology

Department / Any Other (Please

specify)

Private :

Any other (Please specify)

Name : Address :

Phone :

7. Association

• WITH EVENTS

In History

In Rituals :

In Building Construction

Any other (specify) :

WITH PERSONS

Patron :

Architect / Engineer : Any other (specify) :

8. Statement of Significance		
 ✓ Architectural ✓ Archaeological Historical Religious Any other (specify) 	. Pointed arch opening.	
	SECTION II: DESCRIPTION	
9. Physical Description and De	corative Features	
Context Urban√ / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary)	
	Stand in Isolation Integral part of a Landscape / Street / Complex	
• Quantification Area Dimension (L x B x H)	: (m / cm/ feet / inch)	
Number of Blocks Number of Storys	(m/ cm/ leet/ mcn/	
 Spatial Organization Orientation 	: The Gateway is oriented North/South and faces the North.	
Plan Allocation of Spaces	: :	
 ARCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Any Other (specify) 	: : :	
10. Construction Technology		
Structural System	· Indo Darajan	

Structural System
Building Techniques
Material of Construction Indo-Persian Arcuate System Stone.

11. Condition Assessment		
In General	Good / Fair	
	✓ Sign of DeteriorationSerious DeteriorationDanger of Disappearance	
In Brief (Attach extra sheet if necessary):		
Diolapidated.		
12. Threats to the Property		
	Natural Natural	
	√ Negligence	
	Vandalism	
	Urban Pressures	

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS